

AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001700  GROUNDS	ELEVATION : GROUND FLOOR ROOM : BASKETBALL CRT POSITION : SIGNS DESC : COMPRESSED SHEETING ON 2 ONLY BASKETBALL BACKBOARDS	PRODUCT TYPE : COMPRESSED SHEET  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUNDS ROOM : OUTSIDE POSITION : FURNITURE/FIXTURES DESC : COMPRESSED SHEETING ON BBQ SERVERY TOP REFER PHOTO 20	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
2001703 POOL GRANDSTAND 1 POOL GRANDSTAND NO1	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : FURNITURE/FIXTURES DESC : BENCH TO FRONT ENTRY TO GRANDSTAND NO2 REFER PHOTO 16	PRODUCT TYPE : COMPRESSED SHEET  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
2001704 POOL GRANDSTAND 2 POOL GRANDSTAND NO2	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : WALL DESC : SHEETING TO TOP AND BOTH ENDS TO GRANDSTAND NO2 REFER PHOTO 17	PRODUCT TYPE : COMPRESSED SHEET  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001705 POOL CANTEEN POOL CANTEEN	ELEVATION : GROUND FLOOR ROOM : CANTEEN POSITION : FLOOR DESC : SHEET VINYL FLOORING TO POOL CANTEEN REFER TO PHOTO 18 & SAMPLE 1735	PRODUCT TYPE : POLYMER BOUND CONDITION : FAIR SAMPLE RESULT : 1735 NO ASBESTOS DETECTED	PRIORITY : MEDIUM DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : CANTEEN POSITION : CEILING DESC : SHEETING TO CEILING TO POOL CANTEEN	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : PIPE WORK DESC : DRAIN SURROUND TO WESTERN WALL TO POOL CANTEEN REFER PHOTO 15	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : SOFFIT DESC : SOFFIT ON NORTH ASPECT TO POOL CANTEEN	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

Attention  
 Cecile →  
 Bulimba SS  
 Asbestos  
 Damage

~~REPLACED~~

Released

AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001706 POOL AMENITIES CHEMICAL STORE	ELEVATION : GROUND FLOOR ROOM : CHEMICAL STORE POSITION : FURNITURE/FIXTURES DESC : COMPRESSED SHEETING TO SHELVES IN POOL CHEMICAL STORE REFER PHOTO 19	PRODUCT TYPE : COMPRESSED SHEET CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
2001706 POOL AMENITIES POOL AMENITIES	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : PIPE WORK DESC : DRAIN SURROUND ON WESTERN ASPECT OF POOL AMENITIES REFER PHOTO 15	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : PIPE WORK DESC : VENT PIPE ON WESTERN WALL ON AMENITIES BLOCK REFER PHOTO 14	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
2001707 TEACHING C BLOCK	ELEVATION : GROUND FLOOR ROOM : BOYS TOILET POSITION : CEILING DESC : CEILING THROUGHOUT ENTIRE ROOM REFER PHOTO 25	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____



AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001707 TEACHING C BLOCK	ELEVATION : GROUND FLOOR ROOM : BOYS TOILET POSITION : WALL DESC : COMPRESSED SHEETING ON CUBICLE PARTITIONS REFER PHOTO 26	PRODUCT TYPE : COMPRESSED SHEET  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : BOYS TOILET POSITION : FLOOR DESC : WALL SHEETING TO INSIDE PERIMETER WALLS REFER TO PHOTO 25	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : F/STAFF TOILETS POSITION : CEILING DESC : CEILING THROUGHOUT TOILET REFER PHOTO 24	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : F/STAFF TOILETS POSITION : WALL DESC : WALLSHEETING THROUGHOUT ENTIRE TOILET REFER PHOTO 24	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001707 TEACHING C BLOCK	ELEVATION : GROUND FLOOR ROOM : GIRLS TOILET POSITION : CEILING DESC : CEILING SHEETING TO ENTIRE AREA REFER PHOTO 30	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : GIRLS TOILET POSITION : WALL DESC : WALL SHEETING TO PERIMETER WALLS IN TOILETS REFER PHOTO 30	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : GIRLS TOILETS POSITION : WALL DESC : COMPRESSED SHEETING TO CUBICLE REFER PHOTO 31	PRODUCT TYPE : COMPRESSED SHEET  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : PIPE WORK DESC : DRAIN SURROUND TO EAST ASPECT, DRAIN TILTADOOR NORTH ASPECT & DRAIN BACK WALL-WEST-PHOTO 21	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001707 TEACHING C BLOCK	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : WALL DESC : SHADOWLINE TO WESTERN ASPECT UNDER BUILDING REFER SAMPLE 1736	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : 1736 NO ASBESTOS DETECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : WALL DESC : WALL SHEETING AROUND TOILETS & STORE ROOMS UNDER BUILDING REFER PHOTO 23	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : STOREROOM POSITION : CEILING DESC : SHEETING THROUGHOUT ENTIRE ROOM REFER PHOTO 27	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : STOREROOM C 603 POSITION : WALL DESC : WALLSHEETING THROUGHOUT ENTIRE ROOM REFER PHOTO 27	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

Released under the  
 Environmental Protection  
 Information Act

AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001707 TEACHING C BLOCK	ELEVATION : GROUND FLOOR ROOM : STOREROOM C 604 POSITION : WALL DESC : SHADOWLINE WALL SHEETING TO NORTH WALL OF STORE REFER PHOTO 29	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : STOREROOM C 604 POSITION : WALL DESC : WALL SHEETING TO ONE SIDE (SOUTH) OD STORE ROOM REFER PHOTO 28	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : STOREROOM C604 POSITION : CEILING DESC : SHEETING TO CEILING THROUGHOUT ENTIRE ROOM REFER PHOTO 28	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : LEVEL 1 ROOM : OPEN CLASSROOM POSITION : WALL DESC : CEILING THROUGHOUT ENTIRE OPEN CLASSROOM REFER PHOTO 33	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

Release on 20/07/2014



AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001707 TEACHING C BLOCK	ELEVATION : LEVEL 1 ROOM : OPEN CLASSROOM POSITION : FLOOR DESC : <del>SHEET VINYL FLOORING TO ENTRY            OF OPEN CLASSROOM REFER SAMPLE            1737</del> <i>Removed &amp; Replace            with new vinyl flooring</i>	PRODUCT TYPE : POLYMER BOUND CONDITION : FAIR SAMPLE RESULT : 1737 CHRYSOTILE	PRIORITY : MEDIUM DATE : <i>16/07/07</i> SIGNED : <i>[Signature]</i> POSITION : <i>Project Manager</i> CONTRACTOR : <i>Ordehga Repartiles</i> DUMP SITE : <i>Nuchind</i> RECEIPT ID :
	ELEVATION : LEVEL 1 ROOM : OPEN CLASSROOM POSITION : WALL DESC : WALL PANELS TO FRONT ENTRY OF OPEN CLASSROOM REFER PHOTO 32	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : LEVEL 1 ROOM : OPEN CLASSROOM POSITION : WALL DESC : WALLSHEETING TO VARIOUS AREAS TO OPEN CLASSROOM REFER TO PHOTO 34	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : LEVEL 1 ROOM : OUTSIDE POSITION : SOFFIT DESC : SOFFIT AROUND 3/4 BUILDING REFER 22	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____



AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001707 TEACHING C BLOCK	ELEVATION : LEVEL 1 ROOM : STAFFROOM POSITION : FLOOR DESC : <del>SHEET VINYL FLOORING TO STAFF ROOM REFER PHOTO 33</del> <i>Removed + Replaced with new Vinyl sheeting</i>	PRODUCT TYPE : POLYMER BOUND CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : <i>16/04/97</i> SIGNED : <i>[Signature]</i> POSITION : <i>Facet manager</i> CONTRACTOR : <i>Orbus Properties</i> DUMP SITE : <i>None</i> RECEIPT ID :
2001708 TEACHING B BLOCK	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : SOFFIT DESC : SOFFIT OUTSIDE WINDOWS NEAR TUCKSHOP ON SOUTHERN SIDE OF BUILDING	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID :
<i>Removed under BES. QBUILD 2000</i>	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : PIPE WORK DESC : VENT PIPE ON NORTHERN SIDE ABOVE DRINKING TROUGH REFER PHOTO 9	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID :
<i>11 11</i>	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : PIPE WORK DESC : VENT PIPE TO WESTERN ASPECT OF BLOCK B OUTSIDE TUCKSHOP REFER PHOTO 13	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID :

AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST


AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001708 TEACHING B BLOCK	ELEVATION : GROUND FLOOR ROOM : TUCKSHOP POSITION : WALL DESC : PANELS ABOVE SERVERY ON EASTERN SIDE OF TUCKSHOP	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : LEVEL 1 ROOM : OUTSIDE POSITION : SOFFIT DESC : SOFFIT AROUND ENTIRE BUILDING	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : LEVEL 1 ROOM : VERANDAH POSITION : CEILING DESC : SHEETING ON VERANDAH OUTSIDE CLASSROOMS	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
2001709 ADMIN/TEACH ADMIN	ELEVATION : BASEMENT 1 ROOM : BOYS TOILET POSITION : CEILING DESC : CEILING TO ENTIRE BOYS TOILET REFER PHOTO 7	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____



AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001709 ADMIN/TEACH ADMIN	ELEVATION : BASEMENT 1 ROOM : BOYS TOILET POSITION : WALL DESC : COMPRESSED SHEETING ON CUBICLE PARTITIONS IN BOYS AND MALE STAFF TOILETS REFER PHOTO 6	PRODUCT TYPE : COMPRESSED SHEET CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
<i>Removed 2004 as part of Toilet upgrade QBUILD.</i>	<del>ELEVATION : BASEMENT 1 ROOM : BOYS TOILET POSITION : WALL DESC : SHEETING IN ENTRY AROUND SHOWER CUBICLE</del>	<del>PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED</del>	PRIORITY : LOW DATE : <i>27 / 5 / 05</i> SIGNED : <i>Alan QBUILD Supervisor</i> POSITION : _____ CONTRACTOR : _____ DUMP SITE : <i>No Asbestos.</i> RECEIPT ID : _____
<i>" " ?</i>	<del>ELEVATION : BASEMENT 1 ROOM : FEMALE STAFF POSITION : WALL DESC : COMPRESSED SHEETING ON CUBICLE PARTITIONS &amp; EASTERN WALL REFER PHOTO 6</del>	<del>PRODUCT TYPE : COMPRESSED SHEET CONDITION : GOOD SAMPLE RESULT : SUSPECTED</del>	PRIORITY : LOW DATE : <i>27 / 5 / 05</i> SIGNED : <i>Alan QBUILD Supervisor</i> POSITION : _____ CONTRACTOR : _____ DUMP SITE : <i>No Asbestos.</i> RECEIPT ID : _____
	ELEVATION : BASEMENT 1 ROOM : GIRLS TOILET POSITION : CEILING DESC : CEILING IN GIRLS TOILET REFER PHOTO 7 SAMPLE 1731	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

Released

AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001709 ADMIN/TEACH ADMIN	ELEVATION : BASEMENT 1 ROOM : GIRLS TOILET POSITION : WALL DESC : COMPRESSED SHEETING ON CUBICLE PARTITIONS REFER PHOTO 6	PRODUCT TYPE : COMPRESSED SHEET  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
<i>Removed 2005 as part of toilet upgrade QBUILD</i>	ELEVATION : BASEMENT 1 ROOM : GIRLS TOILET POSITION : WALL DESC : WALLSHEETING ON NORTHERN WALL REFER SAMPLE 1732	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : 1732 NO ASBESTOS DETECTED	PRIORITY : LOW DATE : 27/11/05 SIGNED : <i>[Signature]</i> POSITION : <i>QBUILD Supervisor</i> CONTRACTOR : _____ DUMP SITE : <i>No Asbestos.</i> RECEIPT ID : _____
	ELEVATION : BASEMENT 1 ROOM : ROOM 43 POSITION : CEILING DESC : CEILING IN ENTIRE ROOM 43 REFER SAMPLE 1731	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : 1731 MIX OF ASBESTOS TYPE	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : ADMINISTRATION POSITION : CEILING DESC : CEILING IN PRINCIPAL/SECRETARY OFFICE AND ENTRY REFER PHOTO 1 AND SAMPLE 1731	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____



AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001709 ADMIN/TEACH ADMIN	ELEVATION : GROUND FLOOR ROOM : MUSIC ROOM POSITION : CEILING DESC : CEILING IN MUSIC ROOM REFER PHOTO 2 AND SAMPLE 1731	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
<i>Removed BBS 1999-2000 BBuild</i>	<del>ELEVATION : GROUND FLOOR ROOM : ROOM 3 POSITION : FLOOR DESC : SHEET VINYL FLOORING IN STAFF ROOM NEAR SINK REFER PHOTO 5 &amp; SAMPLE 1730</del>	<del>PRODUCT TYPE : POLYMER BOUND  CONDITION : GOOD  SAMPLE RESULT : 1730 NO ASBESTOS DETECTED</del>	<del>PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____</del>
<i>Removed BBS 1999-2000 BBuild</i>	<del>ELEVATION : GROUND FLOOR ROOM : ROOM 8 POSITION : FLOOR DESC : FLOOR TILES IN ROOM 8 REFER PHOTO 3 AND SAMPLE 1728</del>	<del>PRODUCT TYPE : POLYMER BOUND  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED</del>	<del>PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____</del>
	ELEVATION : GROUND FLOOR ROOM : ROOM 9 POSITION : CEILING DESC : CEILING IN ROOM 9 REFER PHOTO 1 AND SAMPLE 1731	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001709 ADMIN/TEACH ADMIN	ELEVATION : GROUND FLOOR ROOM : VARIOUS POSITION : CEILING DESC : CEILING IN ROOMS 3,4,5,6,7 REFER PHOTO 1 AND SAMPLE 1731	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : VERANDAH POSITION : FLOOR DESC : VINYL FLOORING THROUGHOUT ENTIRE VERANDAH & ENTRY REFER PHOTO 4 AND SAMPLE 1729	PRODUCT TYPE : POLYMER BOUND  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : LEVEL 1 ROOM : LIBRARY POSITION : CEILING DESC : CEILINGS THROUGHOUT ENTIRE LIBRARY REFER PHOTO 2 AND SAMPLE 1731	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : LEVEL 1 ROOM : LIBRARY POSITION : FLOOR DESC : FLOOR TILES IN ENTRY TO LIBRARY AND MATHS SCIENCE	PRODUCT TYPE : POLYMER BOUND  CONDITION : GOOD  SAMPLE RESULT : 1728 NO ASBESTOS DETECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

Release on 20/07/2014

AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001709 ADMIN/TEACH ADMIN	ELEVATION : LEVEL 1 ROOM : OUTSIDE POSITION : SOFFIT DESC : SOFFIT AROUND ENTIRE BUILDING REFER PHOTO 8	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : LEVEL 1 ROOM : VARIOUS POSITION : CEILING DESC : CEILINGS THROUGHOUT ENTIRE 1ST FLR CLASSES/STAIRS/PASSAGE REFER PHOTO 1 & SAMPLE 1731	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : LEVEL 1 ROOM : VERANDAH POSITION : FLOOR DESC : VINYL FLOOR THROUGHOUT ENTIRE VERANDAH REFER PHOTO 4	PRODUCT TYPE : POLYMER BOUND CONDITION : GOOD SAMPLE RESULT : 1729 NO ASBESTOS DETECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
2001711 MODULAR NO 1 MODULAR	ELEVATION : GROUND FLOOR ROOM : OPEN CLASSROOM POSITION : CEILING DESC : CEILING THROUGHOUT ENTIRE MODULAR REFER PHOTO 10 AND SAMPLE 1731	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : 1733 NO ASBESTOS DETECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001711 MODULAR NO 1 MODULAR	ELEVATION : GROUND FLOOR ROOM : OPEN CLASSROOM POSITION : FLOOR DESC : VINYL SHEET FLOORING ON BOTH ENTRY'S AND PORT RACK AREA	PRODUCT TYPE : POLYMER BOUND  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : OPEN CLASSROOM POSITION : WALL DESC : WALL SHEETING THROUGHOUT ENTIRE MODULAR REFER PHOTO 11 AND SAMPLE 1734	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : 1734 NO ASBESTOS DETECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : SOFFIT DESC : SOFFIT SHEETING ON NORTH AND SOUTH ASPECT OD MODULAR REFER PHOTO 12	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

NO OF RECORDS REPORTED : 63

PARAMETERS :-

DISTRICT : ME  
 WIC : 2001700

\*\*\*\*\* END OF REPORT \*\*\*\*\*



AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001700 GROUNDS	ELEVATION : GROUND FLOOR ROOM : BASKETBALL CRT POSITION : SIGNS DESC : COMPRESSED SHEETING ON 2 ONLY BASKETBALL BACKBOARDS	PRODUCT TYPE : COMPRESSED SHEET CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
① 2001703 POOL GRANDSTAND 1 POOL GRANDSTAND NO1	ELEVATION : GROUNDS ROOM : OUTSIDE POSITION : FURNITURE/FIXTURES DESC : COMPRESSED SHEETING ON BBQ SERVERY TOP REFER PHOTO 20	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
① 2001703 POOL GRANDSTAND 1 POOL GRANDSTAND NO1	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : FURNITURE/FIXTURES DESC : BENCH TO FRONT ENTRY TO GRANDSTAND NO2 REFER PHOTO 16	PRODUCT TYPE : COMPRESSED SHEET CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
2001704 POOL GRANDSTAND 2 POOL GRANDSTAND NO2	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : WALL DESC : SHEETING TO TOP AND BOTH ENDS TO GRANDSTAND NO2 REFER PHOTO 17	PRODUCT TYPE : COMPRESSED SHEET CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

① removed 13/8/05

AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001705 POOL CANTEEN POOL CANTEEN	④ ELEVATION : GROUND FLOOR ROOM : CANTEEN POSITION : FLOOR DESC : SHEET VINYL FLOORING TO POOL CANTEEN REFER TO PHOTO 18 & SAMPLE 1735	PRODUCT TYPE : POLYMER BOUND CONDITION : FAIR SAMPLE RESULT : 1735 NO ASBESTOS DETECTED	PRIORITY : MEDIUM DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	① ③ ELEVATION : GROUND FLOOR ROOM : CANTEEN POSITION : CEILING DESC : SHEETING TO CEILING TO POOL CANTEEN	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : PIPE WORK DESC : DRAIN SURROUND TO WESTERN WALL TO POOL CANTEEN REFER PHOTO 15	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : SOFFIT DESC : SOFFIT ON NORTH ASPECT TO POOL CANTEEN	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

① For photo 19/5/05 Sample 14391 - Chrysotile Asbestos detected -  
 ② For photo 23/5/05 No Asbestos detected  
 ③ removed ceiling 13/8/05

AUDIT NO : 125 SITE NAME : BULIMBA SS  
 REGION : METROPOLITAN EAST AUDITOR : DAVID BLAIR DATE OF INSPECTION : 07/11/1996  
 ZONE : A ZONE MET EST RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001706 POOL AMENITIES CHEMICAL STORE	ELEVATION : GROUND FLOOR ROOM : CHEMICAL STORE POSITION : FURNITURE/FIXTURES DESC : COMPRESSED SHEETING TO SHELVES IN POOL CHEMICAL STORE REFER PHOTO 19	PRODUCT TYPE : COMPRESSED SHEET CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
2001706 POOL AMENITIES POOL AMENITIES	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : PIPE WORK DESC : DRAIN SURROUND ON WESTERN ASPECT OF POOL AMENITIES REFER PHOTO 15	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : PIPE WORK DESC : VENT PIPE ON WESTERN WALL ON AMENITIES BLOCK REFER PHOTO 14	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
2001707 TEACHING C BLOCK	ELEVATION : GROUND FLOOR ROOM : BOYS TOILET POSITION : CEILING DESC : CEILING THROUGHOUT ENTIRE ROOM REFER PHOTO 25	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

*0 removed 13/8/05*



AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001707 TEACHING C BLOCK	ELEVATION : GROUND FLOOR ROOM : BOYS TOILET POSITION : WALL DESC : COMPRESSED SHEETING ON CUBICLE PARTITIONS REFER PHOTO 26	PRODUCT TYPE : COMPRESSED SHEET  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
<i>1st floor noted crack in wall wet &amp; topped</i>	ELEVATION : GROUND FLOOR ROOM : BOYS TOILET POSITION : FLOOR DESC : WALL SHEETING TO INSIDE PERIMETER WALLS REFER TO PHOTO 25	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : F/STAFF TOILETS POSITION : CEILING DESC : CEILING THROUGHOUT TOILET REFER PHOTO 24	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : F/STAFF TOILETS POSITION : WALL DESC : WALL SHEETING THROUGHOUT ENTIRE TOILET REFER PHOTO 24	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

*1st floor noted 5 diff places*



AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001707 TEACHING C BLOCK	ELEVATION : GROUND FLOOR ROOM : GIRLS TOILET POSITION : CEILING DESC : CEILING SHEETING TO ENTIRE AREA REFER PHOTO 30	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : GIRLS TOILET POSITION : WALL DESC : WALL SHEETING TO PERIMETER WALLS IN TOILETS REFER PHOTO 30	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : GIRLS TOILETS POSITION : WALL DESC : COMPRESSED SHEETING TO CUBICLE REFER PHOTO 31	PRODUCT TYPE : COMPRESSED SHEET  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : CUBICLE POSITION : PIPE WORK DESC : DRAIN SURROUND TO EAST ASPECT, DRAIN TILTADDOOR NORTH ASPECT & DRAIN BACK WALL-WEST-PHOTO 21	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

Release under the RTI Act

AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001707 TEACHING C BLOCK	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : WALL DESC : SHADOWLINE TO WESTERN ASPECT UNDER BUILDING REFER SAMPLE 1736	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : 1736 NO ASBESTOS DETECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : WALL DESC : WALL SHEETING AROUND TOILETS & STORE ROOMS UNDER BUILDING REFER PHOTO 23	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : STOREROOM POSITION : CEILING DESC : SHEETING THROUGHOUT ENTIRE ROOM REFER PHOTO 27	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
<i>Noted hole in wall with hole in wall s. rubble 15/11/96</i>	ELEVATION : GROUND FLOOR ROOM : STOREROOM C 603 POSITION : WALL DESC : WALL SHEETING THROUGHOUT ENTIRE ROOM REFER PHOTO 27	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001707 TEACHING C BLOCK	ELEVATION : GROUND FLOOR ROOM : STOREROOM C 604 POSITION : WALL DESC : SHADOWLINE WALL SHEETING TO NORTH WALL OF STORE REFER PHOTO 29	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : STOREROOM C 604 POSITION : WALL DESC : WALL SHEETING TO ONE SIDE (SOUTH) OD STORE ROOM REFER PHOTO 28	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : STOREROOM C 604 POSITION : CEILING DESC : SHEETING TO CEILING THROUGHOUT ENTIRE ROOM REFER PHOTO 28	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : <b>CH</b> <del>SUSPECTED</del> 30/01/2006 <del>215407-1A-0275</del>	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : LEVEL 1 ROOM : OPEN CLASSROOM POSITION : WALL DESC : CEILING THROUGHOUT ENTIRE OPEN CLASSROOM REFER PHOTO 33	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001707 TEACHING C BLOCK	ELEVATION : LEVEL 1 ROOM : OPEN CLASSROOM POSITION : FLOOR DESC : SHEET VINYL FLOORING TO ENTRY OF OPEN CLASSROOM REFER SAMPLE 1737	PRODUCT TYPE : POLYMER BOUND CONDITION : FAIR SAMPLE RESULT : 1737 CHRYCOTILE	PRIORITY : MEDIUM DATE : / / SIGNED : POSITION : CONTRACTOR : DUMP SITE : RECEIPT ID :
	ELEVATION : LEVEL 1 ROOM : OPEN CLASSROOM POSITION : WALL DESC : WALL PANELS TO FRONT ENTRY OF OPEN CLASSROOM REFER PHOTO 32	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : / / SIGNED : POSITION : CONTRACTOR : DUMP SITE : RECEIPT ID :
	ELEVATION : LEVEL 1 ROOM : OPEN CLASSROOM POSITION : WALL DESC : WALL SHEETING TO VARIOUS AREAS TO OPEN CLASSROOM REFER TO PHOTO 34	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : / / SIGNED : POSITION : CONTRACTOR : DUMP SITE : RECEIPT ID :
	ELEVATION : LEVEL 1 ROOM : OUTSIDE POSITION : SOFFIT DESC : SOFFIT AROUND 3/4 BUILDING REFER 22	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : / / SIGNED : POSITION : CONTRACTOR : DUMP SITE : RECEIPT ID :



AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001707 TEACHING C BLOCK	ELEVATION : LEVEL 1 ROOM : STAFFROOM POSITION : FLOOR DESC : SHEET VINYL FLOORING TO STAFF ROOM REFER PHOTO 35	PRODUCT TYPE : POLYMER BOUND CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
2001708 TEACHING B BLOCK	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : SOFFIT DESC : SOFFIT OUTSIDE WINDOWS NEAR TUCKSHOP ON SOUTHERN SIDE OF BUILDING	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
<i>Removed under BES. Q-Build = 000</i>	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : PIPE WORK DESC : VENT PIPE ON NORTHERN SIDE ABOVE DRINKING TRUGH REFER PHOTO 9	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : PIPE WORK DESC : VENT PIPE TO WESTERN ASPECT OF BLOCK B OUTSIDE TUCKSHOP REFER PHOTO 13	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

*0 Sample 15 Total 23/1/98 - detected refer report.*

AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001708 TEACHING B BLOCK	ELEVATION : GROUND FLOOR ROOM : TUCKSHOP POSITION : WALL DESC : PANELS ABOVE SERVERY ON EASTERN SIDE OF TUCKSHOP	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : LEVEL 1 ROOM : OUTSIDE POSITION : SOFFIT DESC : SOFFIT AROUND ENTIRE BUILDING	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : LEVEL 1 ROOM : VERANDAH POSITION : CEILING DESC : SHEETING ON VERANDAH OUTSIDE CLASSROOMS	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
2001709 ADMIN/TEACH ADMIN	ELEVATION : BASEMENT 1 ROOM : BOYS TOILET POSITION : CEILING DESC : CEILING TO ENTIRE BOYS TOILET REFER PHOTO 7	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

Release under DETE

AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001709 ADMIN/TEACH ADMIN	ELEVATION : BASEMENT 1 ROOM : BOYS TOILET POSITION : WALL DESC : COMPRESSED SHEETING ON CUBICLE PARTITIONS IN BOYS AND MALE STAFF TOILETS REFER PHOTO 6	PRODUCT TYPE : COMPRESSED SHEET CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
<i>Removed 2004 as part of toilet upgrade QBUILD.</i>	ELEVATION : BASEMENT 1 ROOM : BOYS TOILET POSITION : WALL DESC : SHEETING IN ENTRY AROUND SHOWER CUBICLE	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
<i>" " ?</i>	ELEVATION : BASEMENT 1 ROOM : FEMALE STAFF POSITION : WALL DESC : COMPRESSED SHEETING ON CUBICLE PARTITIONS & EASTERN WALL REFER PHOTO 6	PRODUCT TYPE : COMPRESSED SHEET CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : BASEMENT 1 ROOM : GIRLS TOILET POSITION : CEILING DESC : CEILING IN GIRLS TOILET REFER PHOTO 7 SAMPLE 1731	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

*Spoke to Bruce Duncan re update register after refurb. Will contact Adam Underwood to action  
 5/04/05 1.03pm*



AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001709 ADMIN/TEACH ADMIN	ELEVATION : BASEMENT 1 ROOM : GIRLS TOILET POSITION : WALL DESC : COMPRESSED SHEETING ON CUBICLE PARTITIONS REFER PHOTO 6	PRODUCT TYPE : COMPRESSED SHEET  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
<i>Removed 2005 as part of Toilet Upgrade QBUILD</i>	ELEVATION : BASEMENT 1 ROOM : GIRLS TOILET POSITION : WALL DESC : WALLSHEETING ON NORTHERN WALL REFER SAMPLE 1732	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : 1732 NO ASBESTOS DETECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : BASEMENT 1 ROOM : ROOM 43 POSITION : CEILING DESC : CEILING IN ENTIRE ROOM 43 REFER SAMPLE 1731	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : 1731 MIX OF ASBESTOS TYPE	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : ADMINISTRATION POSITION : CEILING DESC : CEILING IN PRINCIPAL/SECRETARY OFFICE AND ENTRY REFER PHOTO 1 AND SAMPLE 1731	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____



AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001709 ADMIN/TEACH ADMIN	ELEVATION : GROUND FLOOR ROOM : MUSIC ROOM POSITION : CEILING DESC : CEILING IN MUSIC ROOM REFER PHOTO 2 AND SAMPLE 1731	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
<i>Removed BBS            1999-2000 BBuild</i>	ELEVATION : GROUND FLOOR ROOM : ROOM 3 POSITION : FLOOR DESC : SHEET VINYL FLOORING IN STAFF ROOM NEAR SINK REFER PHOTO 5 & SAMPLE 1730	PRODUCT TYPE : POLYMER BOUND CONDITION : GOOD SAMPLE RESULT : 1730 NO ASBESTOS DETECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
<i>Removed BBS            1999-2000 BBuild</i>	ELEVATION : GROUND FLOOR ROOM : ROOM 8 POSITION : FLOOR DESC : FLOOR TILES IN ROOM 8 REFER PHOTO 3 AND SAMPLE 1728	PRODUCT TYPE : POLYMER BOUND CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : ROOM 9 POSITION : CEILING DESC : CEILING IN ROOM 9 REFER PHOTO 1 AND SAMPLE 1731	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

Release under RTI Act

AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001709 ADMIN/TEACH ADMIN	ELEVATION : GROUND FLOOR ROOM : VARIOUS POSITION : CEILING DESC : CEILING IN ROOMS 3,4,5,6,7 REFER PHOTO 1 AND SAMPLE 1731	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : VERANDAH POSITION : FLOOR DESC : VINYL FLOORING THROUGHOUT ENTIRE VERANDAH & ENTRY REFER PHOTO 4 AND SAMPLE 1729	PRODUCT TYPE : POLYMER BOUND CONDITION : GOOD SAMPLE RESULT : SUSPECTED <i>MC 0518216</i>	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : LEVEL 1 ROOM : LIBRARY POSITION : CEILING DESC : CEILINGS THROUGHOUT ENTIRE LIBRARY REFER PHOTO 2 AND SAMPLE 1731	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : LEVEL 1 ROOM : LIBRARY POSITION : FLOOR DESC : FLOOR TILES IN ENTRY TO LIBRARY AND MATHS SCIENCE	PRODUCT TYPE : POLYMER BOUND CONDITION : GOOD SAMPLE RESULT : 1728 NO ASBESTOS DETECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

① 1505 21/11/95 - drilled through floor for electrical upgrade

② 19/11/95 - Sample No 4392 - No Asbestos detected - refer report.

AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001709 ADMIN/TEACH ADMIN	ELEVATION : LEVEL 1 ROOM : OUTSIDE POSITION : SOFFIT DESC : SOFFIT AROUND ENTIRE BUILDING REFER PHOTO 8	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
①	ELEVATION : LEVEL 1 ROOM : VARIOUS POSITION : CEILING DESC : CEILINGS THROUGHOUT ENTIRE 1ST FLR CLASSES/STAIRS/PASSAGE REFER PHOTO 1 & SAMPLE 1731	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
②	ELEVATION : LEVEL 1 ROOM : VERANDAH POSITION : FLOOR DESC : VINYL FLOOR THROUGHOUT ENTIRE VERANDAH REFER PHOTO 4	PRODUCT TYPE : POLYMER BOUND CONDITION : GOOD SAMPLE RESULT : 1729 NO ASBESTOS DETECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
③	ELEVATION : GROUND FLOOR ROOM : OPEN CLASSROOM POSITION : CEILING DESC : CEILING THROUGHOUT ENTIRE MODULAR REFER PHOTO 10 AND SAMPLE 1731	PRODUCT TYPE : ASBESTOS CEMENT CONDITION : GOOD SAMPLE RESULT : 1733 NO ASBESTOS DETECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
2001711 MODULAR NO 1 MODULAR			

① replace cabling through ceiling modules  
 ② cleanup performed 5/15/98  
 ③ milled through ground floor verandah, 2nd floor verandah & 2nd floor ceiling for electrical upgrade - 2/15/98  
 ④ tested 2/3/98 Nil detected.



AUDIT NO : 125

SITE NAME : BULIMBA SS

REGION : METROPOLITAN EAST

AUDITOR : DAVID BLAIR

DATE OF INSPECTION : 07/11/1996

ZONE : A ZONE MET EST

RE-AUDIT-DATE : 07/11/1999

BUILDING DETAILS (PLANT NO AND BUILDING NAME)	LOCATION DETAILS	ITEM DETAILS	REMOVAL & FINAL INSPECTION DETAILS (OFFICIAL USE ONLY)
2001711 MODULAR NO 1 MODULAR	ELEVATION : GROUND FLOOR ROOM : OPEN CLASSROOM POSITION : FLOOR DESC : VINYL SHEET FLOORING ON BOTH ENTRY'S AND PORT RACK AREA	PRODUCT TYPE : POLYMER BOUND  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : OPEN CLASSROOM POSITION : WALL DESC : WALL SHEETING THROUGHOUT ENTIRE MODULAR REFER PHOTO 11 AND SAMPLE 1734	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : 1734 NO ASBESTOS DETECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____
	ELEVATION : GROUND FLOOR ROOM : OUTSIDE POSITION : SOFFIT DESC : SOFFIT SHEETING ON NORTH AND SOUTH ASPECT OD MODULAR REFER PHOTO 12	PRODUCT TYPE : ASBESTOS CEMENT  CONDITION : GOOD  SAMPLE RESULT : SUSPECTED	PRIORITY : LOW DATE : ___ / ___ / ___ SIGNED : _____ POSITION : _____ CONTRACTOR : _____ DUMP SITE : _____ RECEIPT ID : _____

NO OF RECORDS REPORTED : 63

PARAMETERS:-

DISTRICT : ME  
 WIC : 2001700

\*\*\*\*\* END OF REPORT \*\*\*\*\*

*① Tested 19/10/95 Sample No 14389 - Vinyl Sheety - No Asbestos detected - See report.*