



expert health and safety advice

Queensland Department of Education
Asbestos Management Plan Review
July 2020

RELEASED UNDER THE RTI ACT

PROJECT/REPORT FOR:

Asbestos Management Plan Review

PREPARED BY:

s47(3)(b) - Contrary
to the Public Interest

Senior Consultant

BApp Science OHS
ChOHSP Prof, RSP (Aust)
Exemplar Certified Principal WHS Auditor
Federal Safety Officer

&

s47(3)(b) -
Contrary to the
Principal

Adjunct Assoc. Professor, University of Queensland
Fellow & Life Member AIHS
MRIMA, RSP (Aust)
RABQSA Lead OHS Auditor

INSTRUCTING CLIENT:

Greg Bell

Director

Regional Operations
Infrastructure Services Branch
Department of Education (Queensland)

DATE:

8 July 2020

BRIEF DESCRIPTION:

A review of the Department of Education's Asbestos Management Plan was undertaken with the view to identifying any opportunities for improvement in relation to its implementation and effectiveness, including consideration for compliance with the requirements of applicable sections of the *Queensland Work Health and Safety Regulation 2011*.

Table of Contents

INTRODUCTION / BACKGROUND	4
DISCUSSION / FINDINGS	5
LEGISLATIVE REQUIREMENTS AND COMPLIANCE	5
1 - GENERAL DUTY RELATING TO EXPOSURE TO AIRBORNE ASBESTOS	6
FINDING #1	6
RECOMMENDATION #1	7
2 - MANAGEMENT OF ASBESTOS RISK	7
FINDING #2	7
RECOMMENDATION #2	8
3 - PRESENCE OF ASBESTOS TO BE INDICATED	8
FINDING #3	8
RECOMMENDATION #3	10
4 - ASBESTOS MANAGEMENT PLAN	11
FINDING #4	11
RECOMMENDATION #4.1	12
RECOMMENDATION #4.2	12
5 - CONTENT OF THE ASBESTOS MANAGEMENT PLAN	13
FINDING #5	13
RECOMMENDATION #5	13
CONCLUSION	14
SUMMARY LIST OF RECOMMENDATIONS	15
APPENDIX 1 - SIGNAGE	16

INTRODUCTION / BACKGROUND

The following report has been prepared for the Queensland Department of Education, Infrastructure Services Branch and details the review undertaken by AusSafe Consulting, of the current asbestos management system (policies, procedures, plan, other associated documents/guidance and instruction and training on asbestos) for schools in Queensland, e.g. Queensland *Department of Education and Training, Asbestos Management, Asbestos Management Plan for DET Facilities* (July 2016). The review also involved related documents including the document referenced in the **Asbestos Management Plan** for Queensland Department of Education owned facilities – **Queensland Government Asbestos Management Policy** for its assets, (May 2014), as well as, a number of Queensland school asbestos registers (available online).

The above-mentioned documents were reviewed with respect to the requirements of the Queensland *Work Health and Safety Act 2011*, the Queensland *Work Health and Safety Regulation 2011*, and *Workplace Health and Safety Queensland, How to manage and control asbestos in the workplace Code of Practice 2011*. Noting also that there is a National Model Code of Practice, of same title and content.

The intent/purpose of this review is to identify opportunities for improvement in the effectiveness and implementation of the Department's asbestos management system – especially and more importantly whether any deficiencies within the Department of Education's (the Department) Asbestos Management Plan (AMP) can be identified and needs to be addressed. This is of particular interest as to whether such deficiencies/gaps could have contributed or allowed a recent occurrence of an unmanaged disturbance of asbestos containing material (ACM) within a school facility. This review is not intended to provide a complete and full review of the AMP with respect to it according with and being in line with the Department's document review/control processes, but rather how, if at all, the asbestos management system and arrangements can be improved.

This report shall make general recommendations that ought to be considered and maybe needing to be accommodated by the Department and does not contain or identify recommendations that consist of a line by line amendment to the system documentation and plan per se. It is a matter for the Department to

section of the Regulation, a finding (and where relevant, commensurate recommendations) will be determined based upon the content of the AMP and related documents.

1 - GENERAL DUTY RELATING TO EXPOSURE TO AIRBORNE ASBESTOS

Part 8.2 General duty

s 420 - Exposure to airborne asbestos at workplace

- (1) A person conducting a business or undertaking at a workplace must ensure that—
- (a) exposure of a person at the workplace to airborne asbestos is eliminated so far as is reasonably practicable; and
 - (b) if it not reasonably practicable to eliminate exposure to airborne asbestos—exposure is minimised so far as is reasonably practicable.

FINDING #1

In Chapter/Section 6 the DET AMP, '6. MANAGING RISKS ASSOCIATED WITH ACM' it details appropriately the day to day management of education facilities (however, see findings in following sections) and the processes for meeting the requirements of the above section via a risk management approach for ACM present within facilities.

In particular, the AMP details a comprehensive framework for managing asbestos-related risks, and includes:

- Identification and registration of ACM (verified school registers)
- Asbestos Warning Signage (However see finding below for Section 424)
- Safe Business Procedures and Work Practices.
- Progressive removal of ACM (based on risk) (risk registers include risk/condition)
- Education and awareness programs.
- Asbestos Registers
- A 'WAAP' (Work Area Access Permit Process) permit process to control building related work (However, see finding #4 and #5 for Section 429)

determine the means and how each recommendation is catered for systematically, if wanting to take up a respective recommendation, either in full, or in part.

DISCUSSION / FINDINGS

A full review of the AMP and associated system documentation mentioned in the above section has been undertaken. However, with the intent/purpose of the review in mind, and to ensure that at the very least deficiencies within the AMP are clearly identified, only a brief description will be provided where there's little room or opportunity for improvement and/or no gaps have been identified, i.e. is effective and likely able to be fully and properly implemented and at the very least compliant with Legislation and the Code of Practice. More focus shall be given to areas of the AMP where AusSafe has identified that improvements ought to be made and/or are required.

Therefore, relevant sections only, as applicable to the development and requirements of an Asbestos Management Plan, or the Legislation and Code of Practice have been included in this review.

LEGISLATIVE REQUIREMENTS AND COMPLIANCE

Firstly, in a general sense and with respect to asbestos as a hazard in the workplace, the WHS Act creates an additional duty for PCBU's with the management or control of the workplace, in which a person with management or control of a workplace must ensure, so far as is reasonably practicable, that the workplace, the means of entering and exiting the workplace (such as the entries to and exits from the workplace) and anything arising from the workplace are without risks to the health and safety of any person.

Chapter 8 'Asbestos' of the Queensland *Work Health and Safety Regulation 2011* (WHSR), details the legislative requirements for a person conducting a business or undertaking (PCBU) with regard to the management of work involving asbestos or ACM.

This Section will review the AMP against the relevant requirements of Chapter 8 of the WHSR, its parts and sections and where required, make reference to the Code of Practice, the Queensland *Work Health and Safety Act 2011*, and other documents for further support and discussion. For each part or relevant

RECOMMENDATION #1

Whilst the AMP and in particular the framework and elements contained within it has been found to be satisfactory and appropriate, there is suspected inadequacies and deficiencies in implementation and embedding the processes and controls at schools and other sites and as such recommendations in the form of Site (School) Specific Implementation Plans being developed and rolled out at each school and even as a refresh for those schools that have been strictly adhering to the AMP.

2 – MANAGEMENT OF ASBESTOS RISK

Part 8.3 Management of Asbestos and associated risks

s 422- Asbestos to be identified or assumed at a workplace

- (1) A person with management or control of a workplace must ensure, so far as is reasonably practicable, that all asbestos or ACM at the workplace is identified by a competent person.
- (2) A person with management or control of a workplace must—
 - (a) if material at the workplace cannot be identified but a competent person reasonably believes that the material is asbestos or ACM—assume that the material is asbestos; and
 - (b) if part of the workplace is inaccessible to workers and likely to contain asbestos or ACM—assume that asbestos is present in the part of the workplace.

FINDING #2

'Section 6.3 - Identification and registration of ACM' and 'Section 6.4 - How do we manage in-situ ACM including periodic inspections', of the AMP, details appropriately the methods for ensuring that all ACM at facilities is identified and reviewed by a competent person and that where the competent person reasonably believes that a material is ACM, or where an inaccessible area is likely to contain ACM, that the competent person can assume the presence of ACM and record it within the asbestos register for the facility. Asbestos registers completed by a competent person have been sighted for this review for a number of facilities that included examples of identified ACM and assumed ACM. This would suggest that the process and requirements of the AMP in this regard can be complied with and has been done so by the few representative examples provided. Nonetheless, this needs to be verified for every location (school or other sites).

RECOMMENDATION #2

Conduct an audit of all registers to:

1. verify the competency of the person who completed and is responsible for the maintaining the register;
2. compare the register with reports to ensure the register is correct; and including
3. check that the register contains entries for assumed ACM, where applicable.

3 – PRESENCE OF ASBESTOS TO BE INDICATED

S424- Presence and location of asbestos to be indicated

A person with management or control of a workplace must ensure that—

- (a) the presence and location of asbestos or ACM identified at the workplace under section 422 is clearly indicated; and*
- (b) if it is reasonably practicable to do so, indicate the presence and location of the asbestos or ACM by a label.*

FINDING #3

As discussed above in response to Section 422 of the Regulation, the AMP details the requirements for a competent person to identify or assume the presence of ACM and enter into a register for a facility, including verified following a review of a register. The examples of registers provided for this review included detailed location descriptors for ACM or assumed ACM. Register requirements within the AMP and verified content within the registers reviewed, met the requirements of Sections 425, 426 and 427 of the Queensland Work Health and Safety Regulation 2011.

'Section 6.5 Asbestos warning signage in schools and workplaces', of the AMP states:

*"The Work Health and Safety Regulation 2011 states a person with management or control of a workplace must ensure the presence and location of asbestos or ACM identified at the workplace is clearly indicated. ... In addition to existing ACM control measures, **ACM warning signage must be installed and maintained** in all department-owned facilities to comply with Work Health and Safety legislation"; and "The Department of Housing and Public Works has advised that the following key elements for ACM warning signage apply:*

- 1. at least one publicly visible sign should be located at the facility's central control point (e.g. reception, front counter etc.), as a minimum;*
- 2. the signs need to be easily visible to anyone who may potentially disturb ACM; and*

3. *the design and size of the signs must comply with Australian Standards.*

It has been accepted that a single sign at the administration centre of the school, ECEC centre or workplace supported by the BEMIR processes for issuing WAAP and viewing the Asbestos Register showing ACM location, type and physical state to all service providers, sufficiently addresses the Queensland legislative requirements”.

However, the first paragraph of section 6.5 of the AMP quotes Section 424 (a) of the Queensland *Work Health and Safety Regulation 2011* but omits Section 424 (b), “if it is reasonably practicable to do so, indicate the presence and location of the asbestos or ACM by a label”. And further to this, the AMP makes no mention of labelling ACM where it is reasonably practicable to do so.

Section 6.5 of the AMP also states that it is acceptable for the posting of a single sign at the administration centre of the school, and that this sufficiently addresses the Queensland legislative requirements. This is not an acceptable stance/position to have in an AMP without further evidence being provided of how this was determined with reference to the ‘so far as is reasonably practicable’ requirement for the use of labels. So, how “it has been accepted” is difficult to understand and in the opinion of AusSafe cannot likely be substantiated. It is counter to the Regulation and Code of Practice and the intent of the need to clearly indicate where asbestos is located for any persons who are exposed to its presence. The caveat on indicating by signage and labelling ‘so far as is reasonably’, is in the context of hidden areas of presence, where a label or sign might need to be placed inside a services cupboard, or on the outside housing of a lift motor with asbestos lined brake pads etc. Placing a sign or label of a skirting board or wall, whilst maybe inconvenient or possibly unsightly, is not impracticable to do.

Further to this, the *Work Health and Safety Regulation 2011*, **Section 429 Asbestos Management Plan - (4)(b)**, states:

“An asbestos management plan must include information relating to the following ... (b) decisions and reasons for decisions, about the management of asbestos at the workplace”.

The AMP does not include/meet the requirement of Section 429(4)(b) with reference to the decision taken to not label ACM where reasonably practicable to do so (as required in S424(b) of the Regulation) and to use a single sign at the administration centre in leu of labelling ACM where it is present in the school.

Further to this finding, The Queensland, *How to Manage and Control Asbestos in the Workplace Code of Practice 2011*, states, inter-alia:

Section 2.5 - Indicating the presence of asbestos in the workplace (which references Section 424 of the Regulation) makes the following statements, (inter-alia):

- If it is reasonably practicable, labels must be used to identify the material as containing asbestos. However, signs may be more appropriate to use.
- Any areas of a workplace that contain asbestos, including plant, equipment and components, should be signposted with warning signs to ensure the asbestos is not unknowingly disturbed without the correct precautions being taken.
- Signs should be placed at all the main entrances to the work areas where asbestos is present.

The Code of Practice also includes in an appendix examples of warning signs and labels (appendix 1 of this review). Acknowledgement is given that these are examples only, however they, as a minimum, provide signage for individual buildings only and not the whole of facility example as per that provided in the Departments AMP.

RECOMMENDATION #3

Consideration must be given to better indicating the presence of asbestos at a school other than by just the displaying of a notice sign at the reception office of the school. This could include a more robust system of detailing the presence and locations more specifically and accurately within a school AMP and register and by way of strict control over access to such areas/locations, including with respect to school staff and contractors entering and working at the school. Buildings and/or rooms could have a sign at entry points indicating whether it has ACM, or assumed ACM, or is asbestos free. And where it is present, the sign need only advise that an authorised access permit is required for any work or potential for disturbance. Messaging about the health hazards and danger of asbestos isn't, in the opinion of AusSafe necessary under such circumstances, i.e. a comprehensive AMP and arrangements for controlling asbestos risks and associated information and communication (including training) being provided to

relevant persons under the AMP. Individual assessment by a competent person is required for each school/facility and incorporated within a specific school/facility AMP.

4 – ASBESTOS MANAGEMENT PLAN

s429 Asbestos Management Plan

(2) A person with management or control of the workplace must ensure that a written plan (an asbestos management plan) for the workplace is prepared.

FINDING #4

This has been met with the completion and provision of the Department's AMP for school/normal business activities - *Department of Education and Training, Asbestos Management, Asbestos Management Plan for DET Facilities* (July 2016).

However, When a Principal Contractor (PC) is appointed for work (construction, demolition or refurbishment), the PC is then determined by Section 293 of the Work Health and Safety Regulation, '**Meaning of principal contractor**', in which, under the *Work Health and Safety Act*, they are a person with management or control of the workplace and therefore under Section 429 of the WHSR have responsibility to develop and manage an Asbestos Management Plan for the work – in case at a Dept of Education facility (school).

This PC AMP would include more detail for the actual work being undertaken by persons under the supervision of the PC and the contents of the AMP would be guided by Section 4.1 of the Code of Practice, '**What is an asbestos management plan**', which states, inter-alia:

An asbestos management plan must include:

- *The identification of asbestos and ACM, for example, a reference or link to the asbestos register for the workplace, and the locations of signs and labels.*
- *Decisions, and reasons for the decisions, about the management of asbestos at the workplace, for example safe work procedures and control measures.*
- *Procedures for detailing accidents, incidents or emergencies of asbestos at the workplace.*

- *Workers carrying out work involving asbestos, for example consultation, information and training responsibilities.*

Note: underlining has been done for this report and does not appear this way in the Code of Practice.

From the review of the Department's AMP it was found that the detail within the document would not provide safe work procedures, as an example, for sub-contractors etc working under an appointed PC (as required above to be in an AMP) and does not require the PC to develop an AMP where ACM has been identified – but merely, the register is provided to PC as per AMP and Regulation requirement.

Also, *Section 5.15 'Principal Contractors/Service Providers'* of the AMP, details that the Principal Contractor is to work under the Department's processes, this clouds the determination of who is in control of the workplace i.e. who is legally the Principal Contractor and not least of all who is the principal PCBU in relation to the work?

RECOMMENDATION #4.1

In addition to the Department AMP (*Department of Education and Training, Asbestos Management, Asbestos Management Plan for DET Facilities [July 2016]*) there ought to be individual site specific AMPs, i.e. for each school/facility which addresses the site specific details, management and plan for ACM, including how and who at the school/facility administers and controls the WAAP and other such things as how, where and by what means the presence of ACM is labelled and signed at the school. It can also incorporate the Register, as well as maintaining the respective record of training and instruction on the AMP at the school. The *Specific School/Facility AMP* must be accompanied by a *Site (School) Specific Implementation Plans* (for site AMP) and roll out at all schools. Furthermore, the Department AMP ought to be amended to incorporate this Recommendation (#4.1).

RECOMMENDATION #4.2

In addition to a *Specific School/Facility AMP*, a PC must also develop their own AMP for any works carried out at a school/facility, in which the Department AMP needs to be amended to incorporate this Recommendation (#4.2), as well as specifying and embedding it within the contract agreement provisions with the PC.

5 – CONTENT OF THE ASBESTOS MANAGEMENT PLAN

s429 'Asbestos Management Plan' of the Work Health and Safety Regulation, and Section 4.1, 'What is an asbestos management plan' of the Code of Practice, provide reasonably brief detailed content requirements for an AMP.

FINDING #5

This has been adequately met by the Department AMP and far exceeds the content requirements of the relevant and applicable regulation and code requirements.

Therefore, the content of the AMP, including the requirements of the legislation and the code of practice, other than omissions identified within earlier findings above, far exceeds these requirements. This can be an issue in relation to the balancing act associated with the autonomy that ought to exist for PC's, but at the same time providing direction and specifications via provision of the plan to contractors etc (as required in section 1.3 of the AMP) for them to read and to carry out their work safely.

The Department AMP contains information that would commonly be found in corporate type procedures and standards for the Department itself, including a comprehensive and detailed permit system, and detailed management training and role description requirements etc. Although as a PCBU with responsibility for the health and safety of school children and staff, there is also the need for ensuring things are done and managed properly. Therefore, providing specifications in the form of performance standards, as well as adequate information and identification of the hazards and risks, ought to be the primary objective, without being too directive where not necessary, i.e. the PC not using Department forms and permits from the Department AMP etc.

RECOMMENDATION #5

Recommendation #4.2 should adequately address the need for this finding.

CONCLUSION

From the review, the following conclusions have been determined by AusSafe Consulting:

- The Department AMP in many circumstances contains information in excess of what is required by the Regulation and the Code of Practice. Consideration could be given to reducing the complexity that comes with the comprehensive nature of the extent of information within the AMP by the development of corporate procedures or standards for incorporating the information that exceeds the requirements of Section 429 of the Regulation, so as to provide a more coherent and effective plan.
- The decision to not label ACM, and further to not sign each work area/building, as per the Regulation and Code of Practice, but rather to post a single sign at the administration office, needs to be better supported, explained and detailed within the AMP, if the Department wishes to continue with this approach. However, it is our opinion that more ought to and can be done in this regard, without necessarily undertaking to sign and label every individual location/area of ACM, which for example, may require more stringent controls and oversight at a school management level for controlling access and permission to carry out work. This would have to include imparting knowledge and information to all staff at the school and monitoring of the condition of ACM at the school.
- The AMP, or other procedure/standard requires the need to detail the process and requirements for the appointment of a Principal Contractor in relation to work where ACM has been identified. This should include the requirement for the development of an AMP from the information provided by the department, e.g. registers and may include the requirement for additional temporary signage to alert workers to the presence of ACM within the PC's area of control.

SUMMARY LIST OF RECOMMENDATIONS

1. **Specific School/Facility AMP** to be developed for each school/facility and the Department AMP needs to be amended to incorporate this requirement, with specifications outlined.
2. An **individual assessment by a competent person** is required for each school/facility for **indicating the presence of ACM**, or otherwise and incorporated within the **Specific School/Facility AMP**.
3. Develop **Site (School) Specific Implementation Plans** (for site AMP) and roll out at all schools.
4. Conduct an **audit of all site asbestos registers** to:
 - a. verify the competency of the person who completed and is responsible for the maintaining the register;
 - b. compare the register with reports to ensure the register is correct; and including
 - c. check that the register contains entries for assumed ACM, where applicable.
5. **Improve the means of indicating the presence of asbestos at a school** other than by just the displaying of a notice sign at the reception office of the school. This could include a more robust system of detailing the presence and locations more specifically and accurately within a school AMP and register and by way of strict control over access to such areas/locations, as well more local signage and labelling. It ought to also include temporary signs/labelling within PC work areas and scope of work.
6. **Principal Contractors must develop their own AMP** for work carried out at a school/facility, which must be informed by and align with the relevant *Specific School/Facility AMP*. The Department AMP needs to be amended to incorporate this requirement, with specifications outlined, as well as supporting contract provisions with Principal Contractors.
7. Schools engagement of Principal Contractors and other contractors (where applicable) must **incorporate provisions within any contract agreement the requirements for PC's** to develop and have their own AMP that conforms with the Department's requirements (above).

- Department of Education
- AMP Review
- July 2020



APPENDIX 1 – SIGNAGE

Examples of warning signs and labels from the Confined Spaces Code of Practice 2011- How to manage and control asbestos in the workplace



Briefing Note

The Honourable Grace Grace MP
Minister for Education and
Minister for Industrial Relations

Action required: For Noting

Action required by: ASAP

Urgent: Information regarding a contentious issue.

SUBJECT: MANAGEMENT OF ASBESTOS CONTAINING MATERIALS IN QUEENSLAND STATE SCHOOLS WITH PARTICULAR REFERENCE TO DUNDULA STATE SCHOOL

Summary of key objectives

- For the Minister to note information relating to asbestos containing materials (ACM) at Dundula State School (SS).

Key issues

1. The Minister has requested the Department of Education (DoE) provide a further and more detailed brief on the matter of alleged asbestos exposure at Dundula SS, including any other claims lodged/settled and any actions taken to engage with the school community about possible exposure.
2. From October 2019 to April 2020, DoE's Infrastructure Services Branch (ISB) provided details for requests for information regarding Dundula SS including a Right to Information (RTI) application, RTI consultation, personal injuries claim and request to clarify information.
3. The various information requests were in relation to records held regarding renovations and construction works carried out and the ACM register for Dundula SS.
4. The information requests also asked for DoE's policies relating to:
 - identifying asbestos; and
 - requirements for entering premises for the purposes of demolition and renovation works.
5. The date range for the request for documents held regarding the ACM register and construction works carried out at Dundula SS is from 1997 to 2004.
6. The RTI consultation request was from the Department of Housing and Public Works (DHPW) and was for access to all documents in relation to any renovations to Dundula SS, including past asbestos registers for the school for the period 1997 to 2004.
7. The ACM register contains 13 entries of confirmed ACM recorded as being removed at Dundula SS. Additionally, there is one entry recorded as no asbestos detected and 12 entries of removal noted as analysis not determined/required. All ACM removal occurred after 2004.
8. An asbestos incident occurred at Dundula SS (outside the information request period) on 19 November 2010. Plumbers were investigating a sink hole after a rain event and uncovered suspected ACM in piping on the school grounds near the administration block. An exclusion area of 10 metres was implemented and temporary fencing erected. Repairs were completed and the incident finalised.

9. A summary of the incident was completed (**Attachment 1**) as well as communication from the Principal, Dundula SS (**Attachment 2**), advising that the incident occurred and contact details were provided.
10. DoE's financial system indicates there were six projects at the school for the period 1997 to 2004. The figures listed below are excluding GST:
 - connection to sewerage – 1998 (\$49,664.76);
 - replacement of amenities block – 1999 (\$175,965.99);
 - temporary accommodation costs – 1999 (\$62,559.11);
 - cooler schools 1999 a/c subsidy program – 2001 (\$65,567.16);
 - cooler schools 2000 a/c subsidy program – 2003 (\$153,078.65); and
 - minor resource centre upgrade to support ICT – 2004 (\$120,383).
11. The Built Environment Materials Information Register (BEMIR) extract as at 30 April 2020 indicates there are three buildings at Dundula SS with ACM confirmed – Blocks A and B and the Prep building (**Attachment 3**).

Media implications

12. On 30 April 2020, an article was published in *The Courier Mail* regarding an ACM claim at Dundula SS.
13. DoE's media team will manage any further queries from the media.

Legal implications s47(3)(a) - Legal Professional Privilege

s47(3)(a) - Legal Professional Privilege

s47(3)(a) - Legal Professional Privilege

Background

20. DPHW's QBuild undertakes ACM audits every three years in accordance with the Asbestos Management Plan (AMP).
21. The last ACM audit was completed in February 2018.

22. ISB provides services that support the ongoing management, maintenance and administration of DoE's assets. This includes management of the physical assets themselves, such as land and buildings. It also includes information about the systems and procedures that support management of assets, such as enrolment management, investment strategies and asbestos management.
23. DoE is committed to ensuring that any ACM found in department-owned facilities is managed in such a way as to minimise the risk to students, staff, service providers, parents/caregivers and other visitors to the site.
24. DoE's AMP provides instructions to building occupants, service providers (e.g. contractors and service personnel) and any other persons whose work or activities may have the potential to disturb ACM, either accidentally or intentionally.
25. The AMP details:
- roles and responsibilities of all DoE staff for the reporting and management of ACM in schools and other department-owned facilities;
 - processes for managing ACM to ensure DoE complies with the legislative requirements while ACM remains in buildings; and
 - processes for managing an asbestos-related incident.
26. Furthermore, relevant staff participate in annual asbestos awareness sessions in schools, and regional offices where facilities are known to have assumed and/or confirmed ACM.
27. BEMIR contains an asbestos register that identifies the assumed or confirmed presence of asbestos within buildings/grounds as well as items that have been removed. The register details the location and physical state for ACM.

RELEASED UNDER THE RTIA ACT

Recommendation

That the Minister **note** the information relating to asbestos containing materials at Dundula State School.

NOTED**APPROVED/NOT APPROVED
ENDORSED/NOTED**

SHARON DURHAM
Chief of Staff
Office of the Hon Grace Grace MP
Minister for Education and
Minister for Industrial Relations

GRACE GRACE MP
Minister for Education and
Minister for Industrial Relations

/ /

/

Minister's comments

--	--	--	--	--

Endorsed by:
 Graham Dredge
 Executive Director

Infrastructure
 Operations
 Ph: (07) 3034 4871
 Date: 28/08/2020

Endorsed by
 Chantal Casey
 A/Assistant Director-
 General
 Infrastructure Services

Ph: (07) 3034 4520
 Date: 01/09/2020

Endorsed by
 Duncan Anson
 A/Deputy Director-
 General
 Corporate Services

Ph: (07) 3034 4771
 Date: 02/09/2020

Endorsed by
 Craig Allen
 A/Deputy Director-
 General
 People and Executive
 Services

Ph: (07) 3034 4774
 Date: 15/09/2020

Endorsed by
 Tony Cook
 Director-General

Ph: (07) 3034 4572
 Date: 16/09/2020

Reference No: **I- 2977**

DETAILS OF INCIDENT

Shop No:

Building: **Dundula State School**

Street No: **Street:1 Main ST**

Locality: **BAKERS CREEK**

Postcode: **4740**

Date and Time of
incident: **19-NOV-2010 09:45**

Controller of
workplace where
incident occurred: **Mr Rodney Finney (Principal)**

Incident description: **PRESUMED ASBESTOS INCIDENT. Contact the Principal directly for more information and updates. After heavy rain yesterday a large sink hole was noticed in the grounds near the Admin building of the school. Q build have engaged Baldocks Plumbing to carry out investigation on what caused the sink hole. After initial investigation by the plumber it was noted that a pipe which is possibly asbestos had a large hole in it which created the ground to wash away at this stage it is only suspected asbestos piping, QBuild have been notified to take samples for testing. Plumbers have put up temporary fencing of exclusion of 10 m around the hole and awaiting on test results and clearance by Q Build Grounds around Admin block. No persons were there due to extra heavy rain the area had no persons in the vicinity Awaiting on Q Build to take testing Once test results known then further advice will be forthcoming. QBuild were notified of the hole and sent plumbers to investigate. Plumbers turned up today to investigate and found that a possible asbestos pipe has a large hole causing the soil to be washed into the pipe - creating a sink hole Will be determined by test results and what QBuild deem necessary to have the site cleared or certified to be reoccupied**

Incident outcome: **Dangerous event**

Incident resulted in
injury to person(s): **No**

**DETAILS OF EMPLOYER, PRINCIPAL
CONTRACTOR OR MAJOR HAZARD FACILITY**

Legal Name:

Trading Name: **Mr Rodney Finney (Principal)**

ABN:

Shop No:

Building: **Dundula State School**

Street No: Street:1 Main ST

Locality: **BAKERS CREEK**

Postcode: **4740**

Phone: **(07) 4952 8333**

Fax:

Email:

Main Business:

DETAILS OF PERSON COMPLETING THIS FORM

First Name: **Bill**

Middle Name:

Surname: **Grant**

Contact phone
number: **07 3237 1813**

Work email address:

Reporting this
incident on behalf of: ☐

Relationship to the
workplace or **WORKER - GOVERNMENT**
incident:

Reporting on behalf
of a Hazard Facility: ☐

[Print](#)
[Finished](#)

RELEASED UNDER THE RTI ACT

Dundula State School (1779)



Ref	New_FLC	Local_Name
01	1779-CA1-S-ADM1	ADMINISTRATION BUILDING
02	1779-CA1-S-PREP	PREP BUILDING
03	1779-CA1-S-AMEN	AMENITIES BUILDING
04	1779-CA1-S-0GR6	PREP STORAGE SHED
05	1779-CA1-S-000B	B BLOCK
06	1779-CA1-S-000A	A BLOCK TEACHING
08	1779-CA1-S-0GR3	SHED SPORTS
09	1779-CA1-S-00GR	GROUNDSMAN SHED
14	1779-CA1-G-GR32	BITUMEN COURTYARD SHADE COVER
16	1779-CA1-G-0GR1	UNDERCOVER PERGOLA
17	1779-CA1-G-GR16	WOODEN COVER OVER SANDPIT
20	1779-CA1-G-0GR2	MULTI-PURPOSE COURTS
21	1779-CA1-G-GR21	PLAYGROUND SHADE COVER PREP-Y
22	1779-CA1-G-00VA	SCHOOL OVAL
23	1779-CA1-S-0RES	RESOURCE BUILDING
25	1779-CA1-G-GR19	LONG JUMP PIT
26	1779-CA1-S-0G15	NEW STORAGE SHED
27	1779-CA1-G-OVA2	SCHOOL OVAL NO 2
28	1779-CA1-S-0GR4	LAWN LOCKER
29	1779-CA1-G-GR17	COVER OVER DUAL SWINGS

Dear Parents/Caregivers

I am writing to inform you that I decided to restrict access to the grounds around the Admin building due to damage caused to an underground stormwater pipe.

Formatted: Justified

The school's Built Environment Materials Information Register (BEMIR) indicates that the pipe may be made of fibro, which may contain asbestos.

Repairs and a professional clean are to be undertaken. The area will remain restricted until a clearance is provided for its reuse.

These precautions will ensure that all students and staff are kept safely away from the area. As you would be aware I take the issue of student and staff safety very seriously. I believe that the partnership we share as a school community means that it is important to keep everyone informed in order to minimise concern.

Please do not hesitate to contact me on 49528355 if you have further queries on this matter.

Yours sincerely

Rod Finney
Principal
Dundula SS

RELEASED UNDER THE RTI ACT

ASBESTOS

REGISTER

for

Department of Education

Region : All
District : All

Current as at: 30/04/2020 10:40:26 AM

Quality Control:	
Document Identification Number
Nominated Officer Name

Record of Asbestos Containing Material printed on 30/04/2020

Agency Name:	Department of Education	Facility:	DUNDULA STATE SCHOOL
Region:	All	Site:	All
District:	All	Improvement:	All
		Improvement Group:	All

Warning Notice: Do not rely solely on the completeness of this Asbestos Register as all asbestos containing material may not be identified and listed, particularly in inaccessible locations and other areas not readily accessed e.g. wall cavities and ceiling spaces. If there is any doubt, presume the material contains asbestos and take appropriate precautions prior to undertaking work. Please read the information contained in the Legends at the end of the Asbestos Register.

RELEASED UNDER THE RTI ACT

Region	District	Facility Name	Site Name	Improvement Agency Name	Improvement Agency Number	Improvement Other Name	Improvement Other Number	Component Int Est	Component Floor Level	Component Specific Location	ACM ID	Description	Item	Form	Analysis Result	Physical State	Status	BSMR Score	Attention Recommended	ACM Identification Date	Last Modified / Entry Date	Comments
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	** Site - Grounds	1779	** Site - Grounds	21779000	Ext	Whole Building (No ACM Identified)	SITE GROUNDS	1122865	SHEETING TO SIGN (DUNDULLA STATE SCHOOL MASONITE - SOUTH SIDE - WEST ELEVATION)	Other (refer to description)	Other (refer to description)	Not Required	NA	Removed	No	No	18/02/2015	20/03/2018 9:02:15 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Ground Floor	(RGOOATS) CANTEEN A BLOCK	807297	CEILING SHEETING - MASONITE	Ceiling	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	28/10/2013	20/03/2018 10:27:32 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Ground Floor	(RGOOATS) CANTEEN A BLOCK	862271	VINYL FLOOR SHEETING (GREY)	Floor Finish/Covering	Other (refer to description)	To be determined	4	Assumed	62	No	14/11/2013	20/03/2018 10:24:59 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Ground Floor	(RGOOATS) CANTEEN A BLOCK	1122678	BITUMINOUS SPRAY - UNDER SINK	Membrane	Sprayed Coating	CHRT - Chrysotile	2	Removed	68	No	10/02/2015	6/05/2015 9:08:38 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Ground Floor	(RGOOATS) CANTEEN A BLOCK	862268	WALL SHEETING - MASONITE - EASTERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 10:28:29 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Ground Floor	(RGOOATS) CANTEEN A BLOCK	862268	WALL SHEETING - MASONITE - NORTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 10:28:19 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Ground Floor	(RGOOATS) CANTEEN A BLOCK	862264	WALL SHEETING - MASONITE - SOUTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 10:27:53 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Ground Floor	(RGOOATS) CANTEEN A BLOCK	143554	WALL SHEETING - MASONITE - WESTERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	27/02/2007	20/03/2018 10:27:17 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A5) STAFF ROOM - A	862091	CEILING SHEETING	Ceiling	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 9:31:52 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A5) STAFF ROOM - A	862097	SHEETING TO CEILING ACCESS PANEL	Ceiling Access Panel	Cement Based	Not determined	3	Removed	18	No	14/11/2013	20/11/2013 12:00:00 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A5) STAFF ROOM - A	862088	VINYL FLOOR SHEETING (GREY)	Floor Finish/Covering	Other (refer to description)	To be determined	3	Assumed	62	No	14/11/2013	20/03/2018 9:31:28 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A5) STAFF ROOM - A	862085	WALL SHEETING - MASONITE - EASTERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 9:34:32 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A5) STAFF ROOM - A	862081	WALL SHEETING - MASONITE - NORTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 9:32:56 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A5) STAFF ROOM - A	862078	WALL SHEETING - MASONITE - SOUTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 9:32:33 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A5) STAFF ROOM - A	862063	WALL SHEETING - MASONITE - WESTERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	13/11/2013	20/03/2018 9:32:18 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A1) CLASSROOM A1	861768	WALL SHEETING - EASTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 9:41:36 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A1) CLASSROOM A1	861766	WALL SHEETING - NORTHERN ELEVATION	Wall	Cement Based	No asbestos detected (NAD)	NA	Not Present (Tested)	No	No	14/11/2013	20/03/2018 9:41:18 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A2) CLASSROOM A2	861807	WALL SHEETING - NORTHERN ELEVATION	Wall	Cement Based	No asbestos detected (NAD)	NA	Not Present (Tested)	No	No	14/11/2013	20/03/2018 9:42:12 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A2) CLASSROOM A2	143565	WALL SHEETING - WESTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	27/02/2007	20/03/2018 9:42:31 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A3) CLASSROOM A3	143723	CEILING SHEETING	Ceiling	Cement Based	CHRT - Chrysotile	4	Confirmed	18	No	27/02/2007	20/03/2018 9:43:04 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A3) CLASSROOM A3	861764	WALL SHEETING - MASONITE - EASTERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 9:44:14 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A3) CLASSROOM A3	861760	WALL SHEETING - MASONITE - SOUTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 9:43:58 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A3) CLASSROOM A3	861977	WALL SHEETING - MASONITE - WESTERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 9:43:21 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A4) CLASSROOM A4	861982	WALL SHEETING - NORTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 9:43:52 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A4) MUSIC ROOM	862128	CEILING SHEETING	Ceiling	Cement Based	CHRT - Chrysotile	3	Confirmed	18	No	14/11/2013	20/03/2018 10:07:22 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A4) MUSIC ROOM	862132	SHEETING TO CEILING ACCESS PANEL	Ceiling Access Panel	Cement Based	Not determined	3	Removed	18	No	14/11/2013	20/11/2013 12:00:00 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A4) MUSIC ROOM	862117	WALL SHEETING - MASONITE - EASTERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 10:09:14 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A4) MUSIC ROOM	862112	WALL SHEETING - MASONITE - NORTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 10:09:00 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A4) MUSIC ROOM	862108	WALL SHEETING - MASONITE - SOUTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 10:08:48 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A4) MUSIC ROOM	862102	WALL SHEETING - MASONITE - WESTERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 10:08:13 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A7) ENCLOSED VERANDAH - EAST	862020	CEILING SHEETING	Ceiling	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 9:56:10 AM	

Region	District	Facility Name	Site Name	Improvement Agency Name	Improvement Agency Number	Improvement Other Name	Improvement Other Number	Component Int. Est.	Component Floor Level	Component Specific Location	ACM ID	Description	Item	Form	Analysis Result	Physical State	Status	BSMR Score	Attention Recommended	ACM Item Position Data	Last Modified / Entry Date	Comments
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A7) ENCLOSED VERANDAH - EAST	862017	VINYL FLOOR SHEETING (LIGHT BLUE)	Floor Finish/Covering	Vinyl Sheeting (includes backing)	To be determined	3	Assumed	62	No	14/11/2013	20/03/2018 9:55:30 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A7) ENCLOSED VERANDAH - EAST	1122592	SHEETING TO HAT AND BAG RACKS - NORTHERN ELEVATION	Furniture	Cement Based	To be determined	4	Assumed	18	No	18/02/2015	20/03/2018 9:56:29 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A7) ENCLOSED VERANDAH - EAST	1122680	SHEETING TO BACKING BOARDS - TO OSB7-AC - SOUTHERN ELEVATION	Wall	Insulation Board	To be determined	3	Assumed	18	No	16/02/2015	20/03/2018 9:56:48 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A7) ENCLOSED VERANDAH - EAST	862012	WALL SHEETING - EASTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 9:49:38 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A7) ENCLOSED VERANDAH - EAST	862010	WALL SHEETING - MASONITE - NORTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 10:00:22 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A7) ENCLOSED VERANDAH - EAST	862005	WALL SHEETING - SOUTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 9:49:15 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A7) ENCLOSED VERANDAH - EAST	861994	WALL SHEETING - WESTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 9:49:43 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A7) REOURCE ROOM	480188	CEILING SHEETING - EASTERN ELEVATION	Ceiling	Cement Based	CHR - Chrysotile	3	Confirmed	18	No	12/07/2011	20/03/2018 10:22:46 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A7) REOURCE ROOM	1122863	VINYL FLOOR SHEETING (BEIGE MOSAIC) - UNDER CARPET	Floor Finish/Covering	Vinyl Sheeting (includes backing)	No asbestos detected (NAZ)	NA	Not Present (Not Tested)	No	No	18/02/2015	20/03/2018 10:24:28 AM	BEIGE MOSAIC
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A7) REOURCE ROOM	862048	WALL SHEETING - MASONITE - EASTERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 10:23:56 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A7) REOURCE ROOM	862043	WALL SHEETING - MASONITE - SOUTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 10:23:26 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A7) REOURCE ROOM	862035	WALL SHEETING - MASONITE - WESTERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 10:23:11 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A8) ENCLOSED VERANDAH - WEST	861939	CEILING SHEETING	Ceiling	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 10:05:42 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A8) ENCLOSED VERANDAH - WEST	861933	VINYL FLOOR SHEETING (LIGHT BLUE)	Floor Finish/Covering	Vinyl Sheeting (includes backing)	To be determined	3	Assumed	62	No	14/11/2013	20/03/2018 10:06:41 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A8) ENCLOSED VERANDAH - WEST	1123250	SHEETING TO HAT AND BAG STORAGE RACK - NORTHERN ELEVATION	Furniture	Cement Based	To be determined	4	Assumed	18	No	18/02/2015	20/03/2018 10:02:43 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A8) ENCLOSED VERANDAH - WEST	861907	WALL SHEETING - EASTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 10:08:15 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A8) ENCLOSED VERANDAH - WEST	861866	WALL SHEETING - MASONITE - EAST END - NORTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 10:05:57 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A8) ENCLOSED VERANDAH - WEST	861862	WALL SHEETING - SOUTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 10:05:20 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A8) ENCLOSED VERANDAH - WEST	861927	WALL SHEETING - WEST END - NORTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 10:06:28 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Int	Level 1	(R1000A8) ENCLOSED VERANDAH - WEST	861859	WALL SHEETING - WESTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 10:01:13 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Ext	Level 1	EXTERNAL (LEVEL 1)	861693	SOFFIT SHEETING - EASTERN ELEVATION	Cable/Soffit/Fascia	Cement Based	To be determined	3	Assumed	18	No	13/11/2013	20/03/2018 9:04:59 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Ext	Level 1	EXTERNAL (LEVEL 1)	861686	SOFFIT SHEETING - NORTHERN ELEVATION	Cable/Soffit/Fascia	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 9:04:43 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Ext	Level 1	EXTERNAL (LEVEL 1)	861679	SOFFIT SHEETING - SOUTHERN ELEVATION	Cable/Soffit/Fascia	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 9:04:12 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Ext	Level 1	EXTERNAL (LEVEL 1)	1123264	BUTTY - TO WINDOWS - SOUTHERN ELEVATION	Membrane	Mastic/Film	No asbestos detected (NAZ)	NA	Not Present (Tested)	No	No	18/02/2015	20/03/2018 9:05:34 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Ext	Level 1	EXTERNAL (LEVEL 1)	1123211	WALL INFILL PANELS - AROUND UPPER WINDOWS - SOUTHERN ELEVATION	Wall	Cement Based	To be determined	4	Assumed	18	No	18/02/2015	20/03/2018 9:05:17 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Ext	Level 1	EXTERNAL VERANDAH - WEST	1267208	CEILING SHEETING	Ceiling	Cement Based	To be determined	4	Assumed	18	No	08/02/2018	20/03/2018 9:08:13 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Ext	Level 1	EXTERNAL VERANDAH - WEST	861580	WALL SHEETING - EASTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 9:08:39 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Ext	Level 1	EXTERNAL VERANDAH - WEST	861575	WALL SHEETING - SOUTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 9:08:05 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Ext	Level 1	EXTERNAL STAIRS	861744	FLOOR SHEETING - LANDING - EAST END - NORTHERN ELEVATION	Floor	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 9:09:10 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Ext	Level 1	EXTERNAL STAIRS	861732	FLOOR SHEETING - LANDING - WEST END - NORTHERN ELEVATION	Floor	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 9:08:46 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Ext	Level 1	OPEN VERANDAH	862258	CEILING SHEETING	Ceiling	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 9:11:06 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Ext	Level 1	OPEN VERANDAH	1122586	SHEETING TO HAT AND BAG RACK - MASONITE - NORTHERN ELEVATION	Furniture	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	18/02/2015	20/03/2018 9:14:04 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Ext	Level 1	OPEN VERANDAH	1122798	SHEETING TO ELECTRICAL BACKING BOARDS - OSB7 - AC - SOUTHERN ELEVATION	Wall	Insulation Board	To be determined	3	Assumed	18	No	18/02/2015	20/03/2018 9:12:36 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Ext	Level 1	OPEN VERANDAH	862253	WALL SHEETING - MASONITE - EASTERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 9:13:41 AM	

Region	District	Facility Name	Site Name	Improvement Agency Name	Improvement Agency Number	Improvement Other Name	Improvement Other Number	Component Ext	Component Floor Level	Component Specific Location	ACM ID	Description	Item	Form	Analysis Result	Physical State	Status	BSMR Score	Attention Recommended	ACM Identification Date	Last Modified / Entry Date	Comments
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Ext	Level 1	OPEN VERANDAH	862249	WALL SHEETING - MASONITE - NORTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 9:13:28 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Ext	Level 1	OPEN VERANDAH	862239	WALL SHEETING - MASONITE - SOUTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 9:13:06 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	A BLOCK TEACHING	1779-CA1-S-000A	A BLOCK TEACHING	21779004	Ext	Level 1	OPEN VERANDAH	862184	WALL SHEETING - WESTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 9:10:44 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	ADMINISTRATION BUILDING	1779-CA1-S-ADM1	ADMINISTRATION BUILDING	21779045	Ext	Whole Building (No ACM Identified)	ADMINISTRATION BUILDING	1271321	BUILDING CONSTRUCTED 2017 - NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	06/02/2018	4/05/2018 9:06:28 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	AMENITIES BUILDING (NEW)	1779-CA1-S-AMEN	AMENITIES BUILDING (NEW)	21779008	Int	Whole Building (No ACM Identified)	AMENITIES BUILDING	1357299	BUILDING CONSTRUCTED 1999 - NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	30/10/2019	30/10/2019 11:28:01 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Int	Ground Floor	(RG000B8) INTERNAL STAIRWELL (GROUND FLOOR)	143322	WALL SHEETING - EASTERN ELEVATION	Wall	Cement Based	CHR - Chrysotile	4	Confirmed	18	No	27/02/2007	20/03/2018 2:35:31 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Int	Ground Floor	(RG000B8) INTERNAL STAIRWELL (GROUND FLOOR)	803928	WALL SHEETING - NORTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	28/10/2013	20/03/2018 2:36:00 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Int	Ground Floor	(RG000B8) INTERNAL STAIRWELL (GROUND FLOOR)	803933	WALL SHEETING - WESTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	28/10/2013	20/03/2018 2:36:15 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Int	Ground Floor	(RG0B5T1) STOREROOM B	862725	CEILING SHEETING	Ceiling	Cement Based	Not determined	3	Removed	18	No	14/11/2013	7/04/2015 2:33:24 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Int	Ground Floor	(RG0B5T1) STOREROOM B	1122332	CEILING SHEETING - SYNTHETIC MINERAL FIBRE (SMF)	Ceiling	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	18/02/2015	20/03/2018 2:56:23 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Int	Ground Floor	(RG0B5T1) STOREROOM B	1122328	WALL SHEETING - MASONITE - SOUTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	18/02/2015	20/03/2018 2:57:39 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Int	Ground Floor	(RG0B5T2) ROAD SAFETY STOREROOM	862717	CEILING SHEETING	Ceiling	Cement Based	Not determined	3	Removed	18	No	13/11/2013	7/04/2015 2:34:45 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Int	Ground Floor	(RG0B5T2) ROAD SAFETY STOREROOM	1122335	CEILING SHEETING - SYNTHETIC MINERAL FIBRE (SMF)	Ceiling	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	16/02/2015	20/03/2018 2:58:56 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Int	Ground Floor	(RG0B5T2) ROAD SAFETY STOREROOM	1122343	VINYL FLOOR SHEETING (MOTTLED BEIGE)	Floor Finish/Carpet	Vinyl Sheeting (includes backing)	To be determined	3	Assumed	62	No	18/02/2015	20/03/2018 2:58:34 PM	MOTTLED BEIGE - ON CONCRETE
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Int	Ground Floor	(RG0B5T2) ROAD SAFETY STOREROOM	1122341	SHEETING TO SPLASHBACK - LAMINATE BOARD - EAST END - NORTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	16/02/2015	20/03/2018 3:00:12 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Int	Ground Floor	(RG0B5T2) ROAD SAFETY STOREROOM	1122338	WALL SHEETING - MASONITE - NORTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	16/02/2015	20/03/2018 2:59:17 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Int	Ground Floor	(RG0B5T2) ROAD SAFETY STOREROOM	862733	WALL SHEETING - SOUTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 2:58:07 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Ext	Ground Floor	EXTERNAL (GROUND)	1122320	CEILING SHEETING - BREEZEWAY - SYNTHETIC MINERAL FIBRE (SMF)	Ceiling	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	16/02/2015	20/03/2018 1:48:33 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Ext	Ground Floor	EXTERNAL (GROUND)	358846	CEILING SHEETING - LINING GROUND FLOOR OPEN AREA	Ceiling	Cement Based	CHR - Chrysotile	4	Removed	18	No	06/11/2008	7/04/2015 2:10:51 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Ext	Ground Floor	EXTERNAL (GROUND)	1122327	CEILING SHEETING - SYNTHETIC MINERAL FIBRE (SMF) - OPEN AREA	Ceiling	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	16/02/2015	20/03/2018 1:51:41 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Ext	Ground Floor	EXTERNAL (GROUND)	862741	SHEETING TO SUNHOOD - NORTHERN ELEVATION	Sun Hood	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 1:48:23 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Ext	Ground Floor	EXTERNAL (GROUND)	862740	SHEETING TO SUNHOOD - SOUTHERN ELEVATION	Sun Hood	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 1:48:44 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Ext	Ground Floor	EXTERNAL (GROUND)	862683	WALL INFILL PANEL - ABOVE ARCHWAY - NORTH SIDE - WESTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 1:48:01 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Ext	Ground Floor	EXTERNAL (GROUND)	1122315	WALL INFILL PANEL - OPEN AREA - ABOVE ARCHWAY - NORTH END - WESTERN ELEVATION	Wall	Cement Based	To be determined	4	Assumed	18	No	16/02/2015	20/03/2018 1:51:18 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Ext	Ground Floor	EXTERNAL (GROUND)	1122322	WALL INFILL PANELS - MASONITE - BREEZEWAY - UPPER SECTION - SOUTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	16/02/2015	20/03/2018 1:49:53 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Ext	Ground Floor	EXTERNAL (GROUND)	1122311	WALL INFILL PANELS - MASONITE - OPEN AREA - UPPER SECTION - NORTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	16/02/2015	20/03/2018 1:48:03 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Ext	Ground Floor	EXTERNAL (GROUND)	1122313	WALL INFILL PANELS - MASONITE - OPEN AREA - UPPER SECTION - SOUTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	16/02/2015	20/03/2018 1:50:16 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Ext	Ground Floor	EXTERNAL (GROUND)	524888	WALL SHEETING - EAST ELEVATION	Wall	Cement Based	CHR - Chrysotile	3	Removed	18	No	20/03/2012	7/04/2015 2:03:26 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Ext	Ground Floor	EXTERNAL (GROUND)	804949	WALL SHEETING - NORTH ELEVATION	Wall	Cement Based	Not determined	3	Removed	18	No	28/10/2013	7/04/2015 2:01:49 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Ext	Ground Floor	EXTERNAL (GROUND)	1122312	WALL SHEETING - OPEN AREA - BY ARTWORK - EASTERN ELEVATION	Wall	Cement Based	To be determined	4	Assumed	18	No	16/02/2015	20/03/2018 1:47:53 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Ext	Ground Floor	EXTERNAL (GROUND)	804957	WALL SHEETING - SOUTH ELEVATION	Wall	Cement Based	Not determined	3	Removed	18	No	28/10/2013	7/04/2015 2:07:01 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-000B	B BLOCK	21779001	Ext	Ground Floor	EXTERNAL (GROUND)	804974	WALL SHEETING - WEST ELEVATION	Wall	Cement Based	Not determined	3	Removed	18	No	28/10/2013	7/04/2015 2:06:18 PM	

Region	District	Facility Name	Site Name	Improvement Agency Name	Improvement Agency Number	Improvement Other Name	Improvement Other Number	Component In Ex	Component Floor Level	Component Specific Location	ACM ID	Description	Item	Form	Analysis Result	Physical State	Status	REMR Score	Attention Recommended	ACM Identification Date	Last Modified / Entry Date	Comments
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Ground Floor	OPEN AREA	862707	CEILING SHEETING	Ceiling	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 2:52:59 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100081) COMPUTER LAB	480254	CEILING SHEETING	Ceiling	Cement Based	CHR - Chrysotile	2	Removed	58	No	02/06/2011	21/11/2013 12:00:00 AM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100081) COMPUTER LAB	1122282	CEILING SHEETING - PLASTERBOARD	Ceiling	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No		16/02/2015	20/03/2018 2:29:36 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100081) COMPUTER LAB	862308	VINYL FLOOR SHEETING (BLUE) - MASONITE	Floor Finish/Covering	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No		14/11/2013	20/03/2018 2:24:00 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100081) COMPUTER LAB	1122287	WALL INFILL PANEL - EAST SIDE - NORTHERN ELEVATION	Wall	Cement Based	To be determined	4	Assumed	18	No	16/02/2015	20/03/2018 2:30:15 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100081) COMPUTER LAB	862662	WALL SHEETING - CENTRAL AREA - NORTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 2:22:18 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100081) COMPUTER LAB	862656	WALL SHEETING - EASTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed		No	14/11/2013	20/03/2018 2:22:37 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100081) COMPUTER LAB	1122285	WALL SHEETING - MASONITE - OUTER SIDES - NORTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No		16/02/2015	20/03/2018 2:29:59 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100081) COMPUTER LAB	862656	WALL SHEETING - MASONITE - SOUTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No		14/11/2013	20/03/2018 2:29:18 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100081) COMPUTER LAB	862654	WALL SHEETING - MASONITE - WESTERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No		14/11/2013	20/03/2018 2:28:22 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100083) CLASSROOM B3	862385	CEILING SHEETING	Ceiling	Cement Based	CHR - Chrysotile	3	Removed	18	No	14/11/2013	09/04/2015 11:04:49 AM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100083) CLASSROOM B3	1122240	CEILING SHEETING - PLASTERBOARD	Ceiling	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No		16/02/2015	20/03/2018 2:08:38 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100083) CLASSROOM B3	862388	VINYL FLOOR SHEETING (BLUE)	Floor Finish/Covering	Vinyl Sheet flooring (includes backing)	To be determined	4	Assumed	62	No	14/11/2013	20/03/2018 2:07:48 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100083) CLASSROOM B3	862375	WALL SHEETING - MASONITE - NORTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No		14/11/2013	20/03/2018 2:08:21 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100083) CLASSROOM B3	862371	WALL SHEETING - MASONITE - SOUTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No		14/11/2013	20/03/2018 2:08:03 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100083) CLASSROOM B3	862366	WALL SHEETING - MASONITE - WESTERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No		14/11/2013	21/03/2018 9:19:56 AM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100083) CLASSROOM B3	862377	WALL SHEETING - TO CONCERTINA FOLDING WALL - EASTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 2:05:56 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100083) ENCLOSED VERANDAH	862431	CEILING SHEETING	Ceiling	Cement Based	CHR - Chrysotile	3	Removed	18	No	14/11/2013	20/11/2013 12:00:00 AM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100083) ENCLOSED VERANDAH	1122237	CEILING SHEETING - PLASTERBOARD	Ceiling	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No		16/02/2015	20/03/2018 2:33:36 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100085) ENCLOSED VERANDAH	862427	VINYL FLOOR SHEETING (BLUE) - MASONITE	Floor Finish/Covering	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No		14/11/2013	20/03/2018 2:32:47 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100085) ENCLOSED VERANDAH	862420	WALL SHEETING - MASONITE - EASTERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No		14/11/2013	20/03/2018 2:32:27 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100085) ENCLOSED VERANDAH	862413	WALL SHEETING - MASONITE - NORTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No		14/11/2013	20/03/2018 2:31:60 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100085) ENCLOSED VERANDAH	862405	WALL SHEETING - MASONITE - SOUTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No		14/11/2013	20/03/2018 2:32:04 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100085) ENCLOSED VERANDAH	862399	WALL SHEETING - MASONITE - WESTERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No		07/11/2013	20/03/2018 2:31:18 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100086) FOYER	863094	CEILING SHEETING	Ceiling	Cement Based	CHR - Chrysotile	3	Removed	18	No	14/11/2013	20/11/2013 12:00:00 AM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100086) FOYER	1122203	CEILING SHEETING - PLASTERBOARD	Ceiling	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No		16/02/2015	20/03/2018 3:05:03 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100086) FOYER	863090	VINYL FLOOR SHEETING (BLUE)	Floor Finish/Covering	Vinyl Sheet flooring (includes backing)	To be determined	4	Assumed	62	No	14/11/2013	20/03/2018 3:04:28 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100086) FOYER	863083	WALL SHEET - EASTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 3:03:06 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100086) FOYER	863072	WALL SHEETING - EAST END - SOUTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 3:02:41 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100086) FOYER	863075	WALL SHEETING - MASONITE - NORTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No		14/11/2013	20/03/2018 3:03:43 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100086) FOYER	1122206	WALL SHEETING - MASONITE - WEST END - SOUTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No		16/02/2015	20/03/2018 3:05:32 PM	
Central Queensland	Central Queensland MacKay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R100086) FOYER	863066	WALL SHEETING - MASONITE - WESTERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No		14/11/2013	20/03/2018 3:03:32 PM	

Region	District	Facility Name	Site Name	Improvement Agency Name	Improvement Agency Number	Improvement Other Name	Improvement Other Number	Component List Ext	Component Floor Level	Component Specific Location	ACM ID	Description	Item	Form	Analysis Result	Physical State	Status	BSMR Score	Attention Recommended	ACM Identification Date	Last Modified / Entry Date	Comments
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R108ST2) STOREROOM	862643	CEILING SHEETING	Ceiling	Cement Based	CHR - Chrysotile	3	Removed	18	No	14/11/2013	20/11/2013 12:00:00 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R108ST2) STOREROOM	862645	VINYL FLOOR SHEETING (BLUE) - MASONITE	Floor Finish/Covering	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	9/04/2016 12:54:03 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R108ST2) STOREROOM	1122215	WALL INFILL PANEL - EAST SIDE - SOUTHERN ELEVATION	Wall	Cement Based	To be determined	4	Assumed	18	No	16/02/2015	20/03/2018 2:53:43 PM	SECOND PANEL FROM EAST SIDE
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R108ST2) STOREROOM	1122224	WALL SHEETING - CENTRE TO WEST END - SOUTHERN ELEVATION	Wall	Cement Based	To be determined	4	Assumed	18	No	16/02/2015	20/03/2018 2:55:45 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R108ST2) STOREROOM	862633	WALL SHEETING - MASONITE - EAST END - SOUTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 2:54:07 PM	SECOND PANEL FROM EAST SIDE
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R108ST2) STOREROOM	862640	WALL SHEETING - MASONITE - EASTERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 2:54:55 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R108ST2) STOREROOM	862636	WALL SHEETING - MASONITE - NORTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 2:54:40 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(R108ST2) STOREROOM	862632	WALL SHEETING - WESTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 2:53:27 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG00056) INTERNAL STAIRWELL (LEVEL 1)	143438	CEILING SHEETING	Ceiling	Cement Based	CHR - Chrysotile	4	Confirmed	18	No	27/02/2007	20/03/2018 2:36:41 PM	DAMAGED AND PATCHED
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG00088) INTERNAL STAIRWELL (LEVEL 1)	862607	WALL SHEETING - EASTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	15/11/2013	21/03/2018 9:07:50 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG00088) INTERNAL STAIRWELL (LEVEL 1)	862606	WALL SHEETING - MASONITE - SOUTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 2:37:38 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG00088) INTERNAL STAIRWELL (LEVEL 1)	862603	WALL SHEETING - NORTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 2:37:22 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG00088) INTERNAL STAIRWELL (LEVEL 1)	862599	WALL SHEETING - WESTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 2:37:06 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG100082) CLASSROOM B2	143766	CEILING SHEETING	Ceiling	Cement Based	CHR - Chrysotile	3	Removed	18	No	27/02/2007	20/11/2013 12:00:00 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG100082) CLASSROOM B2	1122253	CEILING SHEETING - PLASTERBOARD	Ceiling	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	16/02/2015	20/03/2018 2:02:34 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG100082) CLASSROOM B2	862356	SHEETING TO CEILING ACCESS PANEL	Ceiling Access Panel	Cement Based	Not determined	3	Removed	18	No	14/11/2013	20/11/2013 12:00:00 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG100082) CLASSROOM B2	143615	VINYL FLOOR SHEETING (BLUE)	Floor Finish/Covering	Cement Based	Not determined	4	Removed	18	No	27/02/2007	7/04/2015 12:59:30 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG100082) CLASSROOM B2	1122271	VINYL FLOOR SHEETING (BLUE)	Floor Finish/Covering	Vinyl Sheeting (includes backing)	To be determined	4	Assumed	82	No	16/02/2015	20/03/2018 2:04:36 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG100082) CLASSROOM B2	143351	WALL SHEETING - AROUND CONCRETE/WALL - WESTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	27/02/2007	20/03/2018 2:00:33 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG100082) CLASSROOM B2	862344	WALL SHEETING - MASONITE - EASTERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 2:01:29 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG100082) CLASSROOM B2	862340	WALL SHEETING - MASONITE - NORTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 2:01:09 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG100082) CLASSROOM B2	862331	WALL SHEETING - MASONITE - SOUTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 2:00:53 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG100094) BAG RACK ROOM	862627	CEILING SHEETING	Ceiling	Cement Based	CHR - Chrysotile	3	Removed	18	No	14/11/2013	20/11/2013 12:00:00 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG100094) BAG RACK ROOM	1122232	CEILING SHEETING - PLASTERBOARD	Ceiling	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	16/02/2015	20/03/2018 2:00:09 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG100094) BAG RACK ROOM	862624	VINYL FLOOR SHEETING (BLUE)	Floor Finish/Covering	Vinyl Sheeting (includes backing)	To be determined	4	Assumed	62	No	14/11/2013	20/03/2018 1:59:30 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG100094) BAG RACK ROOM	862621	WALL SHEETING - MASONITE - EASTERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 1:58:39 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG100094) BAG RACK ROOM	862618	WALL SHEETING - MASONITE - NORTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 1:58:22 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG100094) BAG RACK ROOM	862616	WALL SHEETING - MASONITE - SOUTHERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	20/03/2018 1:57:43 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 1	(RG100094) BAG RACK ROOM	862611	WALL SHEETING - MASONITE - WESTERN ELEVATION	Wall	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	21/03/2018 9:20:27 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Ext	Level 1	EXTERNAL (LEVEL 1)	143513	SOFFIT SHEETING	Gable/Soffit Fascia	Cement Based	Not determined	4	Removed	18	No	27/02/2007	7/04/2015 11:56:12 AM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Ext	Level 1	EXTERNAL (LEVEL 1)	862688	SOFFIT SHEETING - NORTHERN ELEVATION	Gable/Soffit Fascia	Cement Based	CHR - Chrysotile	3	Confirmed	18	No	14/11/2013	20/03/2018 1:53:36 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Ext	Level 1	EXTERNAL (LEVEL 1)	862694	SOFFIT SHEETING - SOUTHERN ELEVATION	Gable/Soffit Fascia	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 1:54:29 PM	
Central Queensland	Central Queensland Mackay	DUNDULLA STATE SCHOOL	DUNDULLA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Ext	Level 1	EXTERNAL (LEVEL 1)	862698	SOFFIT SHEETING - WESTERN ELEVATION	Gable/Soffit Fascia	Cement Based	CHR - Chrysotile	3	Confirmed	18	No	14/11/2013	20/03/2018 1:53:54 PM	

Region	District	Facility Name	Site Name	Improvement Agency Name	Improvement Agency Number	Improvement Other Name	Improvement Other Number	Component Est	Component Floor Level	Component Specific Location	ACM ID	Description	Item	Form	Analysis Result	Physical State	Status	ECMR Score	Attention Recommended	ACM Identification Date	Last Modified / Entry Date	Comments
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Est	Level 1	EXTERNAL (LEVEL 1)	1122180	WALL INFILL PANEL - BETWEEN WINDOWS - WEST SIDE - NORTHERN ELEVATION	Wall	Cement Based	To be determined	4	Assumed	18	No	16/02/2015	20/03/2018 1:54:57 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Est	Level 1	EXTERNAL (LEVEL 1)	862685	WALL INFILL PANEL ABOVE DOOR - WESTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	20/03/2018 1:54:10 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Est	Level 1	EXTERNAL (LEVEL 1)	1122188	WALL INFILL PANELS - BETWEEN WINDOWS - SOUTHERN ELEVATION	Wall	Cement Based	To be determined	4	Assumed	18	No	16/02/2015	20/03/2018 1:58:21 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Est	Level 1	EXTERNAL (LEVEL 1)	143522	WALL SHEETING - EASTERN ELEVATION	Wall	Cement Based	CHR - Chrysotile	4	Confirmed	18	No	27/02/2007	20/03/2018 1:53:18 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Int	Level 2	TEACHING AREA	307918	VINYL FLOOR SHEETING - BACKING	Floor Finish/Cove	Vinyl Sheeting (includes backing)	CHR - Chrysotile	4	Removed	62	No	14/06/2007	20/04/2018 10:25:53 AM	REMOVE ENTRY AS NEW VINYL HAS BEEN INSTALLED AS PER ASBESTOS AUDIT 06/02/2018.
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	B BLOCK	1779-CA1-S-0008	B BLOCK	21779001	Est	Roof Level 1	EXTERNAL (ROOF LEVEL 1)	143491	ROOF SHEETING (CORRUGATED)	Roof Sheeting	Cement Based	Not determined	3	Removed	18	No	27/02/2007	1/09/2014 12:00:00 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	BITUMEN COURTYARD SHADE COVER	1779-CA1-G-GR32	BITUMEN COURTYARD SHADE COVER	21779010	Est	Whole Building (No ACM Identified)	SHADE STRUCTURE 2 PARADE	813217	STRUCTURE CONSTRUCTED OF METAL - NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	31/10/2013	21/03/2018 8:18:28 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	COVERED LINK BETWEEN PREP & A	1779-CA1-S-OP11	COVERED LINK BETWEEN PREP & A	21779033	Est	Whole Building (No ACM Identified)	COVERED LINK BETWEEN PREP & A	1269533	STRUCTURE CONSTRUCTED OF METAL - NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	06/02/2018	21/04/2018 6:05:45 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	COVERED LINK FROM A BLOCK TO F	1779-CA1-S-GA12	COVERED LINK FROM A BLOCK TO F	21779027	Est	Whole Building (No ACM Identified)	COVERED LINK FROM A BLOCK TO F	1269534	STRUCTURE CONSTRUCTED OF METAL - NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	06/02/2018	21/04/2018 8:09:32 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	COVERED LINK FROM ADMIN TO B	1779-CA1-S-0014	COVERED LINK FROM ADMIN TO B	21779032	Est	Whole Building (No ACM Identified)	COVERED LINK FROM ADMIN TO B BLOCK	1269535	STRUCTURE CONSTRUCTED OF METAL - NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	06/02/2018	21/04/2018 8:10:13 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	COVERED LINK FROM AMENITIES TO	1779-CA1-S-0018	COVERED LINK FROM AMENITIES TO	21779026	Est	Whole Building (No ACM Identified)	COVERED LINK	1269536	STRUCTURE CONSTRUCTED OF METAL - NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	06/02/2018	21/04/2018 8:11:18 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	COVERED LINK FROM B BLOCK TO A	1779-CA1-S-0811	COVERED LINK FROM B BLOCK TO A	21779029	Est	Whole Building (No ACM Identified)	COVERED LINK FROM B BLOCK TO A	1269537	STRUCTURE CONSTRUCTED OF METAL - NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	06/02/2018	21/04/2018 8:11:49 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	COVERED LINK FROM EASTERN DOOR	1779-CA1-S-RE59	COVERED LINK FROM EASTERN DOOR	21779035	Est	Whole Building (No ACM Identified)	COVERED LINK FROM EASTERN DOOR	1269538	STRUCTURE CONSTRUCTED OF METAL - NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	06/02/2018	21/04/2018 8:12:41 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	COVERED LINK FROM RESOURCE TO	1779-CA1-S-RES1	COVERED LINK FROM RESOURCE TO	21779034	Est	Other (refer to description)	COVERED LINK	1269539	STRUCTURE CONSTRUCTED OF METAL - NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	06/02/2018	21/04/2018 8:13:35 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	COVERED LINK ON EASTERN SIDE Q	1779-CA1-S-GA14	COVERED LINK ON EASTERN SIDE Q	21779028	Est	Whole Building (No ACM Identified)	COVERED LINK	1269540	STRUCTURE CONSTRUCTED OF METAL - NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	06/02/2018	21/04/2018 8:14:20 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	COVERED LINK OVER STAIRS EASTERN END OF A BLOCK	1779-CA1-S-GA13	COVERED LINK OVER STAIRS EASTERN END OF A BLOCK	21779009	Est	Whole Building (No ACM Identified)	COVERED LINKS	813246	STRUCTURE CONSTRUCTED OF METAL - NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	31/10/2013	21/03/2018 8:20:21 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	GROUNDSMAN SHED	1779-CA1-S-000R	GROUNDSMAN SHED	21779005	Est	Whole Building (No ACM Identified)	SHED 2 - GROUNDS	813310	STRUCTURE CONSTRUCTED OF METAL - NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	31/10/2013	21/03/2018 8:21:04 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	LAWN LOCKER	1779-CA1-S-00R4	LAWN LOCKER	21779031	Est	Other (refer to description)	LAWN LOCKER	1122681	STRUCTURE CONSTRUCTED OF METAL - NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	16/02/2015	21/03/2018 9:08:32 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	MULTI-PURPOSE COURTS	1779-CA1-G-GR02	MULTI-PURPOSE COURTS	21779021	Est	Whole Building (No ACM Identified)	SPORTS FACILITIES / COURTS	808922	NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	30/10/2013	21/03/2018 8:21:30 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	NEW STORAGE SHED	1779-CA1-S-0015	NEW STORAGE SHED	21779030	Est	Whole Building (No ACM Identified)	STORAGE SHED	1267269	NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	06/02/2018	21/03/2018 8:23:07 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PLAYGROUND SHADE COVER PREP-YEAR 3	1779-CA1-G-GR21	PLAYGROUND SHADE COVER PREP-YEAR 3	21779022	Est	Whole Building (No ACM Identified)	SHADE STRUCTURE NO 1	426621	STRUCTURE CONSTRUCTED OF METAL - NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	06/05/2019	11/07/2019 2:51:14 PM	Building built post 1990
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PLAYGROUND SHADE COVER YEAR 4-7	1779-CA1-G-GR23	PLAYGROUND SHADE COVER YEAR 4-7	21779017	Est	Whole Building (No ACM Identified)	SHADE STRUCTURE 3 - PLAY	813333	STRUCTURE CONSTRUCTED OF METAL - NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	31/10/2013	21/03/2018 8:24:15 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P1) PREP SCHOOL CLASSROOM	1122782	Ceiling SHEETING - NORTH END	Ceiling	Cement Based	To be determined	4	Assumed	18	No	16/02/2015	24/10/2018 3:24:08 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P1) PREP SCHOOL CLASSROOM	861136	Ceiling SHEETING - STRAW COMPOSITE (WHITE)	Ceiling	Other (refer to description)	Not Required	NA	Not Present (Not Tested)	No	No	14/11/2013	21/03/2018 8:57:28 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P1) PREP SCHOOL CLASSROOM	1257902	VINYL FLOOR COVERING UNDER SHELVES	Floor Finish/Cove	Vinyl Sheeting (includes backing)	CHR - Chrysotile	2	Removed	66	No	22/12/2017	24/10/2018 3:24:09 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P1) PREP SCHOOL CLASSROOM	861144	VINYL FLOOR SHEETING (CREAM) - NORTH WEST SECTION	Floor Finish/Cove	Vinyl Sheeting (includes backing)	No asbestos detected (NAD)	NA	Not Present (Tested)	No	No	14/11/2013	24/10/2018 3:42:19 PM	INCLUDES KITCHEN

Region	District	Facility Name	Site Name	Improvement Agency Name	Improvement Agency Number	Improvement Other Name	Improvement Other Number	Component Int Est	Component Floor Level	Component Specific Location	ACM ID	Description	Item	Form	Analysis Result	Physical State	Status	BSMR Score	Attention Recommended	ACM Identification Date	Last Modified / Entry Date	Comments
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P1) PREP SCHOOL CLASSROOM	1122788	VINYL FLOOR SHEETING - NORTH SIDE OF CLASSROOM	Floor Finish/Covering	Vinyl Sheeting (includes backing)	CHR - Chrysotile	3	Removed	62	No	16/02/2015	24/10/2018 3:24:05 PM	NORTHERN SIDE OF CLASSROOM
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P1) PREP SCHOOL CLASSROOM	1282799	VINYL FLOOR SHEETING - UNDER STRUCTURAL STEEL POSTS	Floor Finish/Covering	Vinyl Sheeting (includes backing)	CHR - Chrysotile	3	Confirmed	62	No	06/05/2019	24/10/2018 3:53:50 PM	COULD NOT BE REMOVED. REFER WO 14771165
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P1) PREP SCHOOL CLASSROOM	1122790	BITUMINOUS PAD - BENEATH SINK	Membrane	Mastic/Filler	To be determined	3	Assumed	46	No	16/02/2015	24/10/2018 3:24:09 PM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P1) PREP SCHOOL CLASSROOM	803801	WALL SHEETING - EASTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	28/10/2013	21/03/2018 8:55:12 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P1) PREP SCHOOL CLASSROOM	126749	WALL SHEETING - NORTHERN ELEVATION	Wall	Cement Based	CHR - Chrysotile	4	Confirmed	18	No	20/11/1996	21/03/2018 8:53:35 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P1) PREP SCHOOL CLASSROOM	803795	WALL SHEETING - SOUTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	28/10/2013	21/03/2018 8:54:51 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P1) PREP SCHOOL CLASSROOM	803804	WALL SHEETING - WESTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	28/10/2013	21/03/2018 8:56:09 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P1) PREP SCHOOL CLASSROOM	861550	WALL SHEETING - WING WALL - EASTERN ELEVATION	Wall	Cement Based	CHR - Chrysotile	3	Confirmed	18	No	14/11/2013	21/03/2018 8:54:30 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P1) PREP SCHOOL CLASSROOM	861544	WALL SHEETING - WING WALL - NORTHERN ELEVATION	Wall	Cement Based	CHR - Chrysotile	3	Confirmed	18	No	14/11/2013	21/03/2018 8:53:57 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P1) PREP SCHOOL CLASSROOM	1122775	WALL SHEETING - WING WALL - SOUTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	16/02/2015	21/03/2018 8:57:45 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P1) PREP SCHOOL CLASSROOM	861555	WALL SHEETING - WING WALL - WESTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:56:58 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P2) LADIES TOILETS - PREP	861392	CEILING SHEETING	Ceiling	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:44:35 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P2) LADIES TOILETS - PREP	861387	VINYL FLOOR SHEETING (BEIGE MOSAIC)	Floor Finish/Covering	Vinyl Sheeting (includes backing)	No asbestos detected (NAD)	NA	Not Present (Tested)	No	14/11/2013	21/03/2018 9:17:59 AM	BEIGE MOSAIC - EDGES EXPOSED	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P2) LADIES TOILETS - PREP	861373	WALL SHEETING - EASTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:44:20 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P2) LADIES TOILETS - PREP	861328	WALL SHEETING - NORTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:44:06 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P2) LADIES TOILETS - PREP	861319	WALL SHEETING - SOUTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:43:49 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P2) LADIES TOILETS - PREP	861313	WALL SHEETING - WESTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:43:32 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P2) OFFICE - PREP	861235	CEILING SHEETING	Ceiling	Cement Based	No asbestos detected (NAD)	NA	Not Present (Tested)	No	14/11/2013	21/03/2018 8:53:07 AM		
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P2) OFFICE - PREP	861204	WALL SHEETING - EASTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:52:33 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P2) OFFICE - PREP	861197	WALL SHEETING - NORTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:52:18 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P2) OFFICE - PREP	861189	WALL SHEETING - SOUTHERN ELEVATION	Wall	Cement Based	No asbestos detected (NAD)	NA	Not Present (Tested)	No	14/11/2013	21/03/2018 8:52:47 AM		
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P2) OFFICE - PREP	861183	WALL SHEETING - WESTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:51:59 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P4) STORAGE - PREP	399635	CEILING SHEETING	Ceiling	Cement Based	CHR - Chrysotile	4	Confirmed	18	No	07/04/2010	21/03/2018 9:01:08 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P4) STORAGE - PREP	861171	VINYL FLOOR SHEETING (GREY)	Floor Finish/Covering	Vinyl Sheeting (includes backing)	No asbestos detected (NAD)	NA	Not Present (Tested)	No	14/11/2013	21/03/2018 9:16:17 AM		
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P4) STORAGE - PREP	861165	WALL SHEETING - EASTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 9:05:19 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P4) STORAGE - PREP	861160	WALL SHEETING - NORTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 9:01:55 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P4) STORAGE - PREP	861155	WALL SHEETING - SOUTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 9:01:39 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P4) STORAGE - PREP	861151	WALL SHEETING - WESTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 9:01:23 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P5) STUDENT TOILET - PREP	861514	CEILING SHEETING	Ceiling	Cement Based	To be determined	3	Assumed	18	No	13/11/2013	21/03/2018 8:41:49 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P5) STUDENT TOILET - PREP	1257796	VINYL FLOOR SHEETING	Floor Finish/Covering	Vinyl Sheeting (includes backing)	No asbestos detected (NAD)	NA	Removed	No	16/12/2017	20/04/2018 11:14:09 AM		
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P5) STUDENT TOILET - PREP	186235	VINYL FLOOR SHEETING (BROWN)	Floor Finish/Covering	Other (refer to description)	No asbestos detected (NAD)	NA	Not Present (Tested)	No	20/11/1996	21/03/2018 8:43:07 AM		
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P5) STUDENT TOILET - PREP	1122778	WALL PARTITION - BETWEEN CUBICLES TO TOILETS	Wall	Cement Based	To be determined	3	Assumed	18	No	16/02/2015	21/03/2018 8:42:07 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P5) STUDENT TOILET - PREP	861506	WALL SHEETING - EASTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:41:34 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P5) STUDENT TOILET - PREP	661500	WALL SHEETING - NORTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:41:20 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P5) STUDENT TOILET - PREP	861453	WALL SHEETING - SOUTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:41:07 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P5) STUDENT TOILET - PREP	861494	WALL SHEETING - WESTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:40:48 AM	
Central Queensland	Central Queensland Mackay	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int	Ground Floor	(RG000P6) CLEANERS CUPBOARD	861465	CEILING SHEETING	Ceiling	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:51:33 AM	EXPOSED EDGES AROUND DRAIN PIPE

Region	District	Facility Name	Site Name	Improvement Agency Name	Improvement Agency Number	Improvement Other Name	Improvement Other Number	Component Int. Est.	Component Floor Level	Component Specifics Location	ACM ID	Description	Item	Firm	Analysis Result	Physical State	Status	REMR Score	Attention Recommended	ACM Identification Date	Last Modified / Entry Date	Comments
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int.	Ground Floor	(RG000P6) CLEANERS CUPBOARD	861449	VINYL FLOOR SHEETING (BEIGE MOSAIC)	Floor Finish/Covering	Vinyl Sheeting (includes backing)	To be determined	3	Assumed	62	No	14/11/2013	21/03/2018 8:51:19 AM	BEIGE MOSAIC
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int.	Ground Floor	(RG000P6) CLEANERS CUPBOARD	861428	WALL SHEETING - AROUND DOOR - WESTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:48:38 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int.	Ground Floor	(RG000P6) CLEANERS CUPBOARD	861441	WALL SHEETING - EASTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:49:21 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int.	Ground Floor	(RG000P6) CLEANERS CUPBOARD	861437	WALL SHEETING - NORTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:49:38 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int.	Ground Floor	(RG000P6) CLEANERS CUPBOARD	861434	WALL SHEETING - SOUTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:48:50 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int.	Ground Floor	(RG000P7) LADIES TOILETS - AIRLOCK	861298	CEILING SHEETING	Ceiling	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 9:00:04 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int.	Ground Floor	(RG000P7) LADIES TOILETS - AIRLOCK	861288	VINYL FLOOR SHEETING (BEIGE MOSAIC)	Floor Finish/Covering	Vinyl Sheeting (includes backing)	To be determined	3	Assumed	64	No	14/11/2013	21/03/2018 8:59:52 AM	BEIGE MOSAIC
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int.	Ground Floor	(RG000P7) LADIES TOILETS - AIRLOCK	861268	WALL SHEETING - EASTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:58:31 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int.	Ground Floor	(RG000P7) LADIES TOILETS - AIRLOCK	861274	WALL SHEETING - NORTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:59:29 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int.	Ground Floor	(RG000P7) LADIES TOILETS - AIRLOCK	861260	WALL SHEETING - SOUTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:58:33 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Int.	Ground Floor	(RG000P7) LADIES TOILETS - AIRLOCK	861255	WALL SHEETING - WESTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:58:16 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Ext.	Ground Floor	EXTERNAL (GROUND)	861522	SOFFIT SHEETING - EASTERN ELEVATION	Cable/Soffit/Fascia	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:30:16 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Ext.	Ground Floor	EXTERNAL (GROUND)	126850	SOFFIT SHEETING - NORTHERN ELEVATION	Cable/Soffit/Fascia	Other (refer to description)	No asbestos detected (NOAC)	NA	Not Present (Tested)	No	No	20/11/1996	21/03/2018 8:31:48 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Ext.	Ground Floor	EXTERNAL (GROUND)	861037	SOFFIT SHEETING - SOUTHERN ELEVATION	Cable/Soffit/Fascia	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:30:29 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Ext.	Ground Floor	EXTERNAL (GROUND)	861030	SOFFIT SHEETING - WESTERN ELEVATION	Cable/Soffit/Fascia	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:29:55 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Ext.	Ground Floor	EXTERNAL (GROUND)	861530	WALL INFILL PANEL - SOUTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	14/11/2013	21/03/2018 8:32:04 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Ext.	Ground Floor	EXTERNAL (GROUND)	1122744	WALL INFILL PANEL - UPPER WALL - EASTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	16/02/2015	21/03/2018 8:32:41 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Ext.	Ground Floor	EXTERNAL (GROUND)	1122742	WALL INFILL PANELS - UPPER WALL - SOUTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	16/02/2015	21/03/2018 8:32:25 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Ext.	Ground Floor	EXTERNAL (GROUND)	803755	WALL SHEETING - EASTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	28/10/2013	21/03/2018 8:29:22 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Ext.	Ground Floor	EXTERNAL (GROUND)	126647	WALL SHEETING - NORTHERN ELEVATION	Wall	Cement Based	CHT - Chrysotile	3	Confirmed	40	No	20/11/1996	21/03/2018 8:29:38 AM	THE BOTTOM OF THE SHEETS ON THE EASTERN END HAS BEEN OVERSHEETED TO A HEIGHT OF 0.6 OF A METRE TO DETER FURTHER DAMAGE AS PER INSTRUCTION FROM DET
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Ext.	Ground Floor	EXTERNAL (GROUND)	803748	WALL SHEETING - SOUTHERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	28/10/2013	21/03/2018 8:29:00 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP BUILDING	1779-CA1-S-PREP	PREP BUILDING	21779019	Ext.	Ground Floor	EXTERNAL (GROUND)	803761	WALL SHEETING - WESTERN ELEVATION	Wall	Cement Based	To be determined	3	Assumed	18	No	28/10/2013	21/03/2018 8:29:37 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	PREP STORAGE SHED	1779-CA1-S-00R8	PREP STORAGE SHED	21779008	Ext.	Whole Building (No ACM identified)	SHED 3 - STORAGE	813270	STRUCTURE CONSTRUCTED OF METAL - NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	No Required	NA	Not Present (Not Tested)	No	No	31/10/2013	21/03/2018 9:04:16 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	RESOURCE BUILDING	1779-CA1-S-00R5	RESOURCE BUILDING	21779024	Ext.	Whole Building (No ACM identified)	RESOURCE CENTRE	813239	BUILDING CONSTRUCTED POST 2010 - NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	No Required	NA	Not Present (Not Tested)	No	No	11/12/2013	21/03/2018 9:04:47 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	SCHOOL OVAL	1779-CA1-G-00VA	SCHOOL OVAL	21778023	Ext.	Site / Grounds	OVAL X 2	806897	NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	No Required	NA	Not Present (Not Tested)	No	No	30/10/2013	21/03/2018 9:05:10 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	SCHOOL OVAL NO 2	1779-CA1-G-00VA2	SCHOOL OVAL NO 2	21779044	Ext.	Other (refer to description)	OVAL	1269341	NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	No Required	NA	Not Present (Not Tested)	No	No	06/02/2018	21/04/2018 8:17:38 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	SPORTS SHED	1779-CA1-S-00R3	SPORTS SHED	21779003	Int.	Ground Floor	INTERNAL	1267275	NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	No Required	NA	Not Present (Not Tested)	No	No	06/02/2018	21/03/2018 9:05:48 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	UNDERCOVER PERGOLA	1779-CA1-G-00R1	UNDERCOVER PERGOLA	21779013	Ext.	Whole Building (No ACM identified)	UNDERCOVER PERGOLA	1122870	STRUCTURE CONSTRUCTED OF TIMBER AND CLOTH - NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	No Required	NA	Not Present (Not Tested)	No	No	16/02/2015	21/03/2018 9:06:31 AM	
Central Queensland	Central Queensland	DUNDULA STATE SCHOOL	DUNDULA STATE SCHOOL	WOODEN COVER OVER SANDPIT	1779-CA1-G-GR18	WOODEN COVER OVER SANDPIT	21779014	Ext.	Whole Building (No ACM identified)	COVERED AREA 2 - SANDPIT	813293	STRUCTURE CONSTRUCTED OF METAL - NO ASBESTOS IDENTIFIED	Other (refer to description)	Other (refer to description)	No Required	NA	Not Present (Not Tested)	No	No	31/10/2013	21/03/2018 9:06:51 AM	

	3: Intact and stable, slight damage
	2: reduced stability, degrading
	1: unstable, severely deteriorated or major damage

Safe management of the ACM. It is an assessment of risk that takes into consideration the form of the ACM, the condition of the ACM, and the likelihood of disturbance of the ACM on the date of the asbestos survey/inspection noted in the Asbestos Register.

Type*	Test Results
Bonded	NAD – no asbestos detected
Bonded	CHR – chrysotile
Friable	AMO – amosite
Friable	CHR AMO – chrysotile amosite
Friable	CHR CRO – chrysotile crocidolite
Friable	AMO CRO – amosite crocidolite
Friable	CHR AMO CRO – chrysotile amosite crocidolite
Friable	Mixed – Contains more than one asbestos type**
Bonded	To Be Determined – no sampling and analysis carried out;
Friable	sampling and analysis required to determine ACM
Bonded	Not Determined – no sampling and analysis carried out prior to removal
Friable	Not required – Material confirmed non ACM; sampling and analysis not required
Bonded	
Friable	

* Condition may become friable

** Test required to identify specific asbestos types

Form	Type*	Test Results
AA – Whole Bulkings (asbestos free)		NAD – no asbestos detected
AD – Adhesive	Bonded	CHR – chrysotile
CB – Cement Based	Bonded	AMO – amosite
FF – Fibrous Felt	Friable	CHR AMO – chrysotile amosite
IB – Insulation Board	Friable	CHR CRO – chrysotile crocidolite
LA – Lagging	Friable	AMO CRO – amosite crocidolite
LD – Low Density Board	Friable	CHR AMO CRO – chrysotile amosite crocidolite
LF – Loose Fill	Friable	Mixed – Contains more than one asbestos type**
MF – Mast/Chiller	Bonded	To Be Determined – no sampling and analysis carried out;
MI – Millboard	Friable	Sampling and analysis required to determine ACM presence
PB – Polymer Bound	Bonded	Not Determined – no sampling and analysis carried out prior to removal
SC – Sprayed Coating	Friable	Not required – Material confirmed non ACM; sampling and analysis not required
VS – Vinyl Sheeting (backing)	Friable	
VT – Vinyl Tiles	Bonded	
WT – Woven Textile	Friable	

*Bonded forms of ACM in a deteriorated condition may become friable

** Test required to identify specific asbestos types

Briefing Note

The Honourable Grace Grace MP
Minister for Education
Minister for Industrial Relations and
Minister for Racing

Action required: For Noting

Action required by: ASAP

Urgent: To advise the Minister of an asbestos incident at Berrinba East State School and actions to date.

SUBJECT: BERRINBA EAST STATE SCHOOL ASBESTOS INCIDENT

Summary of key objectives

- For the Minister to note the information and actions to date in relation to an asbestos incident at Berrinba East State School (SS).

Key issues

1. On 11 January 2021, QBuild advised the Department of Education that electrical upgrade works at Berrinba East SS have identified multiple penetrations made through asbestos containing materials during air conditioning installation works completed in March 2020. Test results received on 12 January 2021 are positive.
2. It is understood that an electrical contractor undertaking electrical upgrade works at Berrinba East SS on 9 January 2021 found existing penetrations in asbestos containing materials for new air conditioning pipeworks and cable runs that were completed in March 2020. Relevant areas were immediately locked off and subsequently made safe.
3. The contamination relates to the storeroom areas in B, C, D, F and the Behavioural Support blocks where dust and debris were observed above switchboards below ceiling penetrations.
4. QBuild has made the site safe and locked off the areas.
5. A hygienist has been to the site. The hygienist was to advise QBuild of the scope of works for a full decontamination clean-up and remediation on 12 January 2021.
6. QBuild has engaged an A Class Licensed Asbestos Contractor to complete the clean-up and remediation works from 13 January 2021 under the direction of the hygienist.
7. QBuild has sent the independent consultant Workplace Health and Safety Auditor to site to inspect the areas of the incident and provide an incident report.
8. QBuild has requested the original Principal Contractor (Intrec Management Pty Ltd) raise an incident report with Workplace Health and Safety Queensland (WHSQ).
9. QBuild will provide a full incident report to the department, including a notification number to WHSQ.
10. The department will advise the Principal, Berrinba East SS, of the incident on 13 January 2021 and prepare draft letters to parents of students and staff.
11. The department will work with QBuild and WHSQ on the investigation and remediation.
12. QBuild will also brief the Honourable Mick de Brenni MP, Minister for Energy, Renewables and Hydrogen and Minister for Public Works and Procurement.

Background

13. Berrinba East SS is a school within the 301 schools announced in Priority Air Conditioning Program in November 2019.

Recommendation

That the Minister **note** the information and actions to date in relation to an asbestos incident at Berrinba East State School.

NOTED

**APPROVED/NOT APPROVED
ENDORSED/NOTED**

SHARON DURHAM
Chief of Staff
Office of the Hon Grace Grace MP
Minister for Education
Minister for Industrial Relations and
Minister for Racing

GRACE GRACE MP
Minister for Education
Minister for Industrial Relations and
Minister for Racing

Minister's comments

RELEASED UNDER THE ACT

18/1/2021

Endorsed by:
Chantal Casey
A/ADG
Infrastructure Services

Ph: 3034 4520
Mob: [REDACTED]
Date: 12/01/2021

Endorsed by:
Michael O'Leary
A/DDG
Corporate Services

Ph:
Mob:
Date: 13/01/2021

Endorsed by:
Craig Allen
A/DG

Ph: (07) 3204 4752

Mob:

Date: 13/1/2021